

(SUBMIT IN TRIPLICATE)

Indian Agency _____

	16	
X		

W-3-1
Superior-1
File-1

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Minerals
Allottee **Geologist**
Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 5, 1957

Well No. **W-3-1** is located **1000** ft. from **N** line and **900** ft. from **E** line of sec. **16**

W-3-1 (34 Sec. and Sec. No.) **27N** (Twp.) **2E** (Range) **100W** (Meridian)
Wildcat - (Nebraska) (Field) **Big Springs** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the **well head** above sea level is **7272.0** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill 9-7/8" hole to 4000' and set 3001.25' of 7-1/8" OD 5-25 24.000 8-20 casing w/Huber float collar and guide shoe at 4000.0'. Cemented w/150 cc oil gel and 50 cc water. FOS 4:30 pm 3-12-57. After 30 hours WEL, casing tested okay. Drig ahead.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **WILDCAT PRODUCTION CORP.**

Address **300 Main Building**

Albuquerque, New Mexico

By **RAY PHILLIPS**

Title **Asst. Dir., Prod. Operations**