



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-5178

October 6, 1987

Mr. Ed Barber
Mobil Producing TX & NM, Inc.
P.O. Box 778
Farmington, NM 87499

Re: Jicarilla H #5 M-11-26N-3W
Jicarilla D #7 M-13-26N-3W
Jicarilla E #4 M-11-27N-3W
Jicarilla F #1 B-22-27N-3W
Jicarilla F #5 M-23-27N-3W
Jicarilla G #4 M-26-27N-3W
Jicarilla F #6 A-27-27N-3W
Jicarilla G #1 A-35-27N-3W
Jicarilla G #3 M-35-27N-3W

Dear Mr. Barber:

Annual packer leakage tests on the referenced wells were inconclusive in proving zone separation.

Please reschedule and retest the wells in such a manner as to prove zone separation. Shut in both zones for a minimum of 3 days. Blow the higher pressured zone to the atmosphere or through a separator for as long as it takes to drop the pressure to at least 50 PSI less than the shut in zone.

Notify this office at least 24 hours prior to tests, so we may provide a witness.

Your truly,

Charles Gholson
Deputy Oil & Gas Inspector

CG/dj

xc: Well Files