Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENTS

FORM APPROVED edget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Design SF 079366
6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS 25 Por

Use "APPLICATION FOR PERMIT—" for such proposals and the proposals	
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well	Rincon Unit
Oil Gas X Other	8. Well Name and No.
2. Name of Operator	Rincon Unit
Union Oil Company of California	9. API Well No.
3. Address and Telephone No.	8
3300 N. Butler, Suite 200, Farmington, NM 87401 (505) 326-7600	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Blanco Mesa Verde
	11. County or Parish, State
1450' FSL & 1450' FWL $2C-27N-6V$	
	Rio Arriba, NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intel®D) E G E IV E X Abandonment	Change of Plans
Recompletion	New Construction
Subsequent Reparts ADD 2 Q 1001 Plugging Back	Non-Routine Fracturing
APR2 9 1991 Casing Repair	Water Shut-Off

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Other

Altering Casing

Well has been P&A'd as per BLM approved procedure.

Final Abandonment Cont. DIV.

Approved as to plugging of the well bers. Liebility under bond is retained until surface restoration is completed.

Conversion to Injection

Dispose Water

4/3/91 MIRU BedfordP&A rig.

Set cement retainer at 4600'. Could not pump below retainer. BLM approved following. Spot 37 sx (44 ft³) class "B" cement from 4600'-4408'. Spotted 9.0 ppg mud from 4408'-4042'. Spotted 30 sx (35 ft³) class "B" cement from 4042'-3883'. Shot 3 squeeze holes at 3073'. Set cement retainer at 3020'. Casing leak above 3020' indicated. Squeezed 54 sx (64 ft³) below retainer and spotted 23 sx (27 ft³) above retainer from 3020'-2900'. Shoot 3 squeeze holes at 2827'. Set cement retainer at 2788'. Squeezed 35 sx (41 ft³) class "B" cement below retainer and spotted 12 sx (14 ft³) above retainer at 2788'-2724'. Shoot 3 squeeze holes at 2520'. TIH with tubing to 2538'. Spot 100 sx (118 ft³) class "B" cement from 2538'-2004'. Displace 30 sx (35 ft³) into perfs. Shot 4 squeeze holes at 1182'. Spotted 54 sx (64 ft³) from 1190'-902'. Displace 25 sx (29 ft³) cement into perfs. TOC at 1035'. Shot 3 squeeze holes at 174'. Pump 95 sx (112 ft³) class "B" cment down 7" casing and circulate 10 sx to surface. Cut off casing. Set P&A marker

4/10/91 Release rig. Will rehabilitate location at proper time.	APPROVED_	
4 I hereby certify that the foregoing is true and correct Signed S.G. Katire is Title Petroleum Engineer	Date4/23/91	STEEL STEEL
(This space for Federal or State office use) Approved by Title Conditions of approval, if any:	APR 2/5 1991 Date AREA MANAGER	Contract of the second
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United Sor representations as to any matter within its jurisdiction.	unter kny false, rictitious of fraudrulent state	ment

*See Instruction on Reverse Side

NMOCD