

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well GAS	5. Lease Number SF-079298C 6. If Indian, All. or Tribe Name 7. Unit Agreement Name
2. Name of Operator Meridian Oil Inc.	8. Well Name & Number Ripley #2Y 9. API Well No.
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	10. Field and Pool S. Blanco Pic. Cliff 11. County and State Rio Arriba Co, NM
4. Location of Well, Footage, Sec., T, R, M 1065'FNL, 1650'FEL Sec.24, T-27-N, R-7-W, NMPM	

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other -
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

06-23-92 MOL&RU. Blow down. ND WH. NU BOP. TOOH w/1 1/4" tbg. SDFN.

06-24-92 TIH to 3226'. Cmt plug #1 w/23 sx Class "B" neat w/2.5% calcium chloride 3226-3003'. Displace w/10 BW. WOC. SDFN.

06-25-92 Tag TOC @ 3163'. Pump 10 BW. Cmt plug #2 w/60 sx Class "B" neat 3163-2647'. Displace w/9 BW. PU to 2466'. Load hole w/watr. Try to PT csg, press up to 500#, bled off in 5 min. TOOH. Perf 2 holes @ 2530'. Set cmt ret @ 2466'. PT tbg 1500#, sting into ret, est rate. Cmt plug #3 w/48 sx Class "B" neat, locked up while pumping displacement. Squeeze press to 2000#, 24 sx under ret, sting out, dump 24 sx on top of ret. TOC @ 2265'. Spot 25 bbl 9# 50 vis mud 2265-1390'. Try to PT csg, same as before.

06-26-92 Perf 2 holes @ 1390'. Set cmt ret @ 1323'. Est rate @ 1.5 BPM @ 1100 psig. Pump 4 BW, press up to 2000 psig, held. Sting out. Cmt plug #4 w/12 sx Class "B" neat, spot on top of ret. TOC @ 1223'. Spot 9# 50 vis mud to surf. Perf 2 holes @ 150'. Cmt plug #5 w/26 sx Class "B" neat down 5 1/2" csg & out bradenhead, circ 1 bbl good cmt out bradenhead. Cut off WH. Install dry hole marker w/15 sx. Well plugged & abandoned.

Approved as to plugging of the well bore.
Liability under bond is retained until
restoration is completed.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 6/26/92

(This space for Federal or State Office use)
APPROVED BY _____ Title _____
CONDITION OF APPROVAL, if any:

APPROVED
Date

JUL 07 1992
[Signature]
AREA MANAGER

NMOCD