| Form | 9-331 |
|------|-------|
| (May | 1963) |

## UNITED STATES SUBMIT IN TRIPLICATE\* Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

Rio Arriba

New Mexico

SF 079492-B 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

|        | GEOL    | OGICAL | SURVEY  |    | ·     |
|--------|---------|--------|---------|----|-------|
| SUNDRY | NOTICES | AND    | REPORTS | ON | WELLS |

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

| Use "AP                              | PLICATION FOR PERMIT—" for such proposals.)                   |  |
|--------------------------------------|---|--|
| OIL GAS X OTH                        | HER   | 7. UNIT AGREEMENT NAME San Juan 27-5 Unit  |
| 2. NAME OF OPERATOR El Paso Natur    | cal Gas Company   | 8. farm or lease name San Juan 27-5 Unit   |
|                                      | Farmington, NM 87401  | 9. WELL NO. 31 (PM)  |
| See also space 17 below.) At surface | ation clearly and in accordance with any State requirements.* | 10. FIELD AND FOOL, OR WILDCAT Blanco Mesa Verde Tapacito Pictured Cliffs 11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 24, T-27-N, R-5-W NMPM |
| 14. PERMIT NO.                       | 15. ELEVATIONS (Show whether DF, RT, GR, etc.)                | 12. COUNTY OR PARISH 13. STATE   |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: |   | SUBSEQUENT REPORT OF: |   |  |  |   |
|-------------------------|---|-----------------------|---|--|--|---|
|                         |   | 1                     |   | 1  |  |   |
| TEST WATER SHUT-OFF     | - | PULL OR ALTER CASING  |   | WATER SHUT-OFF                             | REPAIRING WELL   | _ |
| FRACTURE TREAT          |   | MULTIPLE COMPLETE     |   | FRACTURE TREATMENT                         | ALTERING CASING  |   |
| SHOOT OR ACIDIZE        |   | ABANDON*              |   | SHOOTING OR ACIDIZING                      | ABANDONMENT*   |   |
| REPAIR WELL             |   | CHANGE PLANS          | X | (Other)Tubing I                            |  |   |
| (Other)                 |   | •                     |   | (Note: Report resul<br>Completion or Recon | ts of multiple completion on Well apletion Report and Log form.) |   |

6578'GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

The tubing scab which was set on February 4, 1972 failed to stop the tubing leak. The scab was pulled, the packoffs were redressed, and the scab was reset at 2626' to 2638'.

A packer leakage test concluded on March 23, 1972 indicated that communication still exists between zones.

It is planned to move a rig on this well about March 29, 1972 to replace leaki tubing and/or packer seal assemblies.

MAR 2 4 1972

U. S. GEULUCIONE SURVEY

and correct TITLE Petroleum Engineer DATE March 24, 1972 (This space for Federal or State office use) APPROVED BY DATE CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side