Additional data for EC transaction #7178 that would not fit on the form

32. Additional remarks, continued

1.9" broach on sand line and RIH to 250'. TOH with 10 stands and RIH with 1.9" broach to SN. Shut in well. SDFD.

08-17 Open up well and blow down 180# tubing and casing pressure. Rabbit and RIH with 10 stands; knocked out chunk of rubber from 7th stand, RD tongs. RU 1.9" broach and RIH to SN at 3199' Land 107 joints 2-3/8" EUE tubing with slim hole collars, at 3199' with muleshoe and SN on bottom. ND BOP. NU wellhead and shut in well. RD and MOL. No BLM representative was on location.