

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
Meridian Oil Inc.

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
1650'N, 1850'E Sec.8 , T-27-N, R-5-W, NMPM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment

Type of Action

☐ Abandonment ☐ Change of Plans
☐ Recompletion ☐ New Construction
☐ Plugging Back ☐ Non-Routine Fracturing
☐ Casing Repair ☐ Water Shut off
☐ Altering Casing ☐ Conversion to Injection
☒ Other - Repair Well

13. Describe Proposed or Completed Operations

A rig will be moved onto this dual Mesa Verde - Dakota well within the next 90 days in order to repair a tubing leak. The well failed its 1991 packer leakage test, but the failure is believed to be located in the Dakota string of tbq. The tubing will be pulled and replaced with new tbq. The tbq and packer will then be tested and the well will be returned to dual production according to regulations.

RECEIVED

JUN - 9 1992

OIL CON. DIV.,
DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] (KS) Title Regulatory Affairs Date 5-22-92

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

CONDITION OF APPROVAL, if any: _____

APPROVED

JUN 11 1992
AREA MANAGER