UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Not	ices and Reports	on Wells		
1. Type of Well GAS	200 KAR 070 F/S	27 FK 2: 17	5.	Lease Number SF-079391 If Indian, All. or Tribe Name
2. Name of Operator		£ 26 27 28 ★	7.	Unit Agreement Name
BURLINGION	& GAS COMPANY	APR 2000 RECEIVE OIL OON, DI		San Juan 27-5 Unit Well Name & Number
3. Address & Phone No. of Opera PO Box 4289, Farmington, NM		DIET. S		San Juan 27-5 U #7 API Well No. 30-039-07131
4. Location of Well, Footage, S 1650'FNL, 1850'FEL, Sec.8, T		PM II II D		Field and Pool Blanco MV/Basin DK County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO IN			OTHER	DATA
Type of Submission _X_ Notice of Intent	Type Abandonment Recompletic		of Pl	
Subsequent Report	Plugging Ba	ack Non-Ro	outine	Fracturing
Final Abandonment		asing Conve	rsion t	o Injection
It is intended to comming A down-hole commisstipulations.	gle the subject we	ell according to will be applied	o the a	ttached procedure. Please provide surfa
Signed Jegry Cale		ue and correct.	isor	Date 3/24/00
(This space for Federal or Sta APPROVED BY /S/ Charle E CONDITION OF APPROVAL, if any:	eechan itle		Date _	APR 20 200
Title 18 U.S.C. Section 1001, makes it a crime for the United States any false, fictitious or fraudul	any person knowingly and wilent statements or representati	llfully to make any depar tions as to any matter wi	tment or ag thin its ju	ency of risdiction.

San Juan 27-5 Unit #70

MV/DK

1650 FNL, 1850' FEL Unit G, Section 8, T-27-N, R-05-W

Latitude / Longitude: 36° 35.47212' / 107° 22.7289' Asset Completion Number: 5340302 MV / 5340301 DK

Summary/Recommendation:

San Juan 27-5 Unit #70 was drilled and completed as a MV/DK dual producer in 1962. A 2-1/16" string was landed for the DK, while a 1-1/4" string was landed for the MV. In 1992 the well was pulled because of a production packer leak; however the original 1-1/4" tubing string and a portion of the original 2-1/16" tubing string was landed. In 1993 a swabbing unit couldn't get any deeper than 170° in the 1-1/4" tubing. Within the last year total production has dropped approximately 166 Mcfd. During the workover, the packer will be removed, both zones will produce up a new 2-3/8" tubing string and a plunger lift system will be installed. Anticipated uplift is 166 Mcfd.

- 1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. Haul to location 7900', 2-3/8", 4.7#, J-55, EUE tubing. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. (A single-tubing donut and WH for 2-3/8" tubing will be needed.) Test secondary seal and replace/install as necessary.
- Mesaverde 1-1/4" tubing is set at 5739'. TOOH with 177 jts 1-1/4", 2.3#, JCW-50, IJ tubing and LD MV tubing. Dakota 2-1/16" tubing is set at 7762'. Pick straight up on DK tubing to release the seal assembly from the 4-1/2". Baker Model "D" packer set at 5871'. TOOH with 243 jts, 2-1/16", 3.25#, JCW-50, IJ tubing. Lay down tubing and seal assembly. Send MV and DK tubing strings in to town for inspection and possible salvage. Check tubing for scale build up and notify Operations Engineer.
- 4. PU and TIH with 2-3/8" tubing and Baker Model "CJ" packer milling tool to recover the 4-1/2" Baker Model "D" packer at 5871'. Mill on packer with air/mist using a minimum mist mist rate of 12 bph. TOOH and lay down packer.
- 5. TIH with 3-7/8" bit, bit sub and watermelon mill for 4-1/2", 11.6# casing on 2-3/8" tubing and round trip to PBTD at 7846'. Clean out with air/mist as necessary. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- 6. PU and TIH with a notched expendable check, one joint 2-3/8", 4.7#, J-55, EUE tubing, F-Nipple, then ½ of the 2-3/8" tubing. Run a broach on sandline to insure the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace bad joints as necessary. CO to PBTD with air/mist using a minimum mist rate of 12 bph. Alternate blow and flow periods at PBTD to check water and sand production rates.
- 7. Land tubing at ± 7775'. ND BOP and NU single-tubing hanger WH. Pump off expendable check. Obtain final pitot gauge up the tubing. Connect to casing and circulate air to assure that the expendable check has pumped off. If well will not flow on its own, make swab run to F-Nipple. RD and MOL. Return well to production.

Recommended:

Operations Engineer

Approved:

Approved:

Drilling Superintender

Jennifer L. Dobson

Office - (599-4026)

Home - (564-3244)

Pager - (324-2461)

Sundry Required:

NO

JLD/plh