


Form 9-331a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 079393  
Unit \_\_\_\_\_



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL <del>Water Well</del> <b>XX</b>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<b>FINAL - WATER WELL</b> <b>XX</b>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 10, 19 51

Harrington  
Well No. 1 is located 700 ft. from SW line and 660 ft. from E line of sec. 4  
SE, SE, Sec. 4 27 N. 5 W. N. M. P. M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wilcox Rio Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ----- ft. (Unknown)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 276' of 7" LM Casing - perforated

Pump 8 B W P H

Water Zone: 250' to Total Depth (276')

*Water well near Gas well*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company General American Oil Co. of Texas

Address c/o Mr. John A. Egan

Hillcrest Courts

Farmington, New Mexico

By John A. Egan

JOHN A. EGAN

Title Agent

1. The first part of the report discusses the importance of maintaining accurate records of all transactions. It emphasizes that this is crucial for ensuring the integrity of the financial statements and for providing a clear audit trail. The report also highlights the need for regular reconciliations and the use of appropriate accounting standards.

2. The second part of the report focuses on the internal control system. It outlines the key components of a robust internal control framework, including the segregation of duties, the establishment of clear policies and procedures, and the implementation of effective monitoring mechanisms. The report stresses that a strong internal control system is essential for preventing errors and fraud, and for ensuring the reliability of the financial data.

3. The third part of the report addresses the issue of transparency and disclosure. It discusses the importance of providing timely and accurate information to stakeholders, and the role of the auditor in ensuring that the financial statements are free from material misstatements. The report also touches upon the need for clear communication and the importance of maintaining a good working relationship with the management and the board of directors.

4. The final part of the report provides a summary of the key findings and recommendations. It reiterates the importance of a strong internal control system and the need for transparency and disclosure. The report also offers practical advice on how to implement these principles effectively, and it concludes by emphasizing the role of the auditor in ensuring the integrity of the financial reporting process.