

Drig Engr:
Drig Supt:
Resv Engr:
Prod Engr:
Prod Supt:

Rocky Mountian Group CONDITION OF HOLE

August 21, 1997

FIELD:	San Juan Basin		LEASE:	Rincon Un	it '	WELL NO:	#198	
Location:	Sec 32, T27N, R6	W	. County:	Rio Arriba		- State:	New Mexico	
Survey:	Salt Lake Meridian					-		
REASON F	OR WORK: To	plug and a	bandon.					
CONDITION	OF HOLE:	•						
	TOTAL DEPTH:	3275'	ETD:	3265'	KB DATUM:	10.0'	_ Above: _	G.L.(6677.0)
	CASING RECOR	D :						
	8-5/8" @ 133'. 24	# J-5 5. Cm	nt'd w/90 sx.	Cement C	irc.			
	2-7/8" @ 3275'. 6	.4# J-55 8rd	d. Cmt'd w	/134sx. TO	C @ 2405'.			
	PERFORATIONS							
	Formation	Date	From	То	# Holes			
	Picture Cliffs	Date	3,156	3,226	# 110.C3	Open		

TUBING DETAIL: See Detail wellbore diagram