

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-2827-6

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator El Paso Natural Gas Company 3. Address of Operator P.O. Box 4289, Farmington, New Mexico 87499-4289 4. Location of Well UNIT LETTER K 1590 FEET FROM THE South LINE AND 1560 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 27N RANGE 7W NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 6591' GL	7. Unit Agreement Name 8. Farm or Lease Name San Juan 28-7 Unit 9. Well No. #172 10. Field and Pool, or Wildcat Pictured Cliffs-Chacra 12. County RA
--	--

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) - SEE RULE 1103.

- 1) Circulate Chacra side w/9.0 ppg mud. Spot 57 sacks cement plug from 2112'-4169' (Chacra top @ 4018'-PC top @ 3040'-Ojo Alamo top @ 2162').
- 2) Circulate PC side w/9.0 ppg mud. Spot 31 sacks cement plug from 2112'-3232'.
- 3) Perforate 4 squeeze holes in Chacra side @ 176'.
- 4) Pump 85 sacks cement down. Chacra side and circulate annulus from 176' to surface.
- 5) Spot 5 sacks cement plug in PC side from 176' to surface.
- 6) Install dry hole marker.
- 7) Clean and reseed location.

RECEIVED

JUN 04 1984

OIL CON. DIV.
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Douglas W. Mussett

TITLE Production Engineer

DATE 6-4-84

APPROVED BY Original Signed by FRANK T. CHAVEZ

TITLE

SUPERVISOR DISTRICT # 3

DATE JUN 04 1984

CONDITIONS OF APPROVAL, IF ANY: