

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name San Juan 28-6 Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name San Juan 28-6 Unit
3. Address of Operator P. O. Box 990, Farmington, New Mexico 87401	9. Well No. 195
4. Location of Well UNIT LETTER 0, 825 FEET FROM THE S LINE AND 1800 FEET FROM THE E LINE, SECTION 13 TOWNSHIP 27N RANGE 6W NMPM.	10. Field and Pool, or Wildcat South Blance PC
15. Elevation (Show whether DF, RT, GR, etc.) 6314 GR	12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐


PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER Installation of siphon string ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On May 16, 1979, 94 joints (2996') of 1 1/4" EUE tubing and a 2 7/8" Guiberson packer (set at 3006') were installed in this well as a siphon string.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nestor Maldonado TITLE Production Engineer DATE 7-20-79

Not Approved

AUG 1 1979

CONDITIONS OF APPROVAL: ANY: *Shirley installation is in violation of Rule 108. See attached Memo #3-70. Frank S. Chavez*