### UNITED STATES

## DEPARTMENT OF THE INTERIOR

Sundry Not	ices and Reports on Wells		
Type of Well GAS	16.6 20.31 S.2	5.	Lease Number SF-080673 If Indian, All. or Tribe Name
GAS	2001 ED	7.	Unit Agreement Name
Name of Operator	S NO CENTON	တံ	
	& GAS COMPANY	8.	San Juan 27-4 Unit Well Name & Number San Juan 27-4 U #12
Address & Phone No. of Opera PO Box 4289, Farmington, NN	4 87499 (505) 326-9700	9.	
		10	30-039-21031 Field and Pool
Location of Well, Footage, S 1850'FSL, 1690'FWL, Sec.8, 5	Sec., T, R, M I-27-N, R-4-W, NMPM		Tapacito Pict Cliff Blanco Mesaverde County and State
		11.	Rio Arriba Co, NM
Final Abandonment	Altering Casing Com X_ Other - Commingle		to Injection
		a to the	attached
It is intended to commin procedure. A down the Oil Conserva	ngle the subject well accordin n hole commingle application w	g to the a	attached lbmitted to
It is intended to commin procedure. A down the Oil Conservation	ngle the subject well accordin n hole commingle application w	g to the a	attached ubmitted to
It is intended to commin procedure. A down the Oil Conserva	ngle the subject well accordin n hole commingle application w	g to the a	attached Nomitted to
It is intended to commin procedure. A down the Oil Conservation	ngle the subject well accordin n hole commingle application w	g to the a	attached ubmitted to
It is intended to commin procedure. A down the Oil Conservation	ngle the subject well accordin n hole commingle application w	g to the a	attached ubmitted to
It is intended to commin procedure. A down the Oil Conservation	ngle the subject well accordin n hole commingle application w	g to the a	attached hbmitted to
It is intended to commin procedure. A down the Oil Conservation	ngle the subject well accordin n hole commingle application w	g to the a	attached abmitted to
It is intended to commin procedure. A down the Oil Conservation	ngle the subject well accordin n hole commingle application w	g to the a	attached abmitted to
It is intended to commin procedure. A down the Oil Conservation	ngle the subject well accordin n hole commingle application w	g to the a	attached abmitted to
It is intended to commin procedure. A down the Oil Conservation	ngle the subject well accordin n hole commingle application w	g to the a	attached abmitted to
It is intended to commin procedure. A down the Oil Conservation	ngle the subject well accordin n hole commingle application w	g to the a	attached abmitted to
It is intended to commin procedure. A down the Oil Conservation of the Oil Con	ngle the subject well according the hole commingle application we tion Division.		attached abmitted to
It is intended to commin procedure. A down the Oil Conservation of the Oil Con	ngle the subject well accordin n hole commingle application w		attached abmitted to
It is intended to commin procedure. A down the Oil Conservation of the Oil Con	The foregoing is true and corr  (TF8) Title Regulatory Su	ect.	MH
It is intended to commin procedure. A down the Oil Conservation of the Oil Con	The foregoing is true and corr  (TF8) Title Regulatory Su	ect.	MH

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

# San Juan 27-4 Unit #124 Blanco Mesaverde /Tapacito Pictured Cliffs 1850' FSL' FNL, 1690' FWL Unit K, Sec. 8, T-27-N, R-4-W

Latitude / Longitude: 36° 35.1234' / -107° 16.5804' AIN: 5333301 MV / 5333302 PC

#### Summary/Recommendation:

San Juan 27-4 Unit #124 was drilled and completed as a MV/PC dual producer in 1977. In order to optimize production it is recommended to remove the packer, produce both zones up the MV 2-3/8" tubing string. Currently, the Mesaverde is producing 79 MCF/D and 5.4 BBL/MMCF condensate, and production from the Pictured Cliffs is 40 MCF/D. Anticipated uplift is 39 MCF/D from the Mesaverde and 21 MCF/D from the Pictured Cliffs.

### NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 11'.

- 1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Cole 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. (A single-tubing donut and WH for 2-3/8" tubing will be needed.) Test secondary seal and replace/install as necessary.
- 3. Set a plug with wireline in MV tubing "F" nipple at 6069'. Pick up 1-1/4" tubing and RIH to the top of the Model "D" packer to check for fill. TOOH with 1-1/4", 2.33#, V-55 PC tubing and LD same if fill is not encountered. If fill is present, TOOH with tubing, remove perf'd joint and RIH with open ended tubing. Circulate fill off of the packer and TOOH laying down 1-1/4" tubing. Pick straight up on 2-3/8", 4.7#, J-55 MV tubing set at 6105' (SN @ 6069') to release seal assembly from Baker Model "D" packer set at 3760'. TOOH and stand back 2-3/8" tubing. LD seal assembly. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer and Drilling Superintendent if it is present.
- 4. PU and TlH with 2-3/8" tubing and Baker Model "CJ" packer milling tool to recover the 7" Baker Model "D" packer at 3760'. Mill on packer with air/mist using a minimum mist rate of 12 bph. TOOH and lay down packer.
- 5. PU 3-7/8" bit and bit sub on 2-3/8" tubing string and round trip to PBTD (6154'), cleaning out with air/mist. **NOTE: When using air/mist, minimum mist rate is 12 bph.** If scale is present, contact Operations Engineer and Drilling Superintendent to determine methodology for removing scale from casing and perforations.
- 6. TIH with an expendable check on bottom, seating nipple, one joint 2-3/8", 2' x 2-3/8" pup joint, then ½ of the 2-3/8" tubing. Run a broach on sandline to insure the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace bad joints as necessary. CO to PBTD with air/mist using a minimum mist rate of 12 bph. Alternate blow and flow periods at PBTD to check water and sand production rates.
- 1. Land tubing at 5770'. ND BOP and NU single-tubing hanger WH. Pump off expendable check. Obtain final pitot gauge up the tubing. Connect to casing and circulate air to assure that the expendable check has pumped off. If well will not flow on its own, make swab run to seating nipple. During cleanout operations the reservoir may be charged with air. As a result of excess oxygen levels that may be in the reservoir and/or wellbore, contact the Lease Operator to discuss the need for determining oxygen levels prior to returning the well to production. RD and MOL. Return well to production.

MH

Recommended:

Approved:

Druce D. Boyu 9.25-01 Drilling Superintendent

Tim Friesenhahn

Office - (326-9539)

Pager - (326-8113)

Approved:

Sundry Required: YES NO

Lease Operator:

Ken Spencer

Gabe Archibeque Ken Johnson

Specialist: Foreman:

Cell: 320-2513 Cell: 320-2478 Pager: 327-8901

Pager: 326-8256

Cell: 320-2567

Pager: 324-7676