

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE  
(Other instructions on re-  
verse side)Form approved,  
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 080673

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|  |  |
|--|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER  | 7. UNIT AGREEMENT NAME<br>San Juan 27-4 Unit                                     |
| 2. NAME OF OPERATOR<br>El Paso Natural Gas Company   | 8. FARM OR LEASE NAME<br>San Juan 27-4 Unit                                      |
| 3. ADDRESS OF OPERATOR<br>P. O. Box 990, Farmington, New Mexico 87401  | 9. WELL NO.<br>125 (PM)  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.<br>See also space 17 below.)<br>At surface<br>1550' N, 1717' E | 10. FIELD AND POOL, OR WILDCAT<br>Undes P.C. & Blanco MV                         |
| 14. PERMIT NO.   | 11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA<br>Sec. 8, T-27-N, R-4-W<br>NMPM |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>6968' GL   | 12. COUNTY OR PARISH<br>Rio Arriba   |
|  | 13. STATE<br>New Mexico  |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other) Packer repair

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*


Because of communication between zones, the following repair work was done:

11-26-76 Pulled 1 1/4" tubing.

11-27-76 Pulled 2 3/8" tubing and packer seal assembly. Ran new Baker Model "D" Packer set in 7" casing at 3966'.

11-28-76 Ran 195 joints of 2 3/8", 4.7#, Class "B" Mesa Verde tubing, 6294' set at 6305' with blast joints across upper zone casing perfs.

Ran 123 joints 1 1/4", V-55, 2.33#, Pictured Cliffs tubing, 3892' set at 3903'.



18. I hereby certify that the foregoing is true and correct

SIGNED N. J. BiscoTITLE Drilling ClerkDATE November 30, 1976.

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side