

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985.

6. LEASE DESIGNATION AND SERIAL NO.

SF - 078048

9. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

PORK CHOP

9. WELL NO.
#2

10. FIELD AND POOL, OR WILDCAT
Ballard-Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 29 T26N R7W

12. COUNTY OR PARISH 13. STATE
Rio Arriba New Mexico

1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR
TEXACO INC.

3. ADDRESS OF OPERATOR
P. O. BOX EE, CORTEZ, CO. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1640' FSL 1860 FEL

RECEIVED

JUN 25 1986

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

7083' GR

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Request extended SI Status

FULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco Inc. requests your approval for an extended shut-in status for the Pork Chop Well #2. The well is capable of producing gas in paying quantities, however due to the poor gas market demand the purchaser has requested the well be shut-in indefinitely. The integrity of the casing is believed to be good. The last Braidenhead test submitted August 1983 indicated no flow and the well flows produced, water only. The Pork Chop lease is comprised of two wells and both are shut-in.

APPROVED
AS AMENDED

JUL 21 1986

JUL 23 1986

OIL CON. DIV. AREA MANAGER
DIST. 3

This Approval Expires

7-21-87

18. I hereby certify that the foregoing is true and correct

SIGNED Chas R. Marx

TITLE AREA SUPERINTENDENT

DATE 6/24/86

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

BLM (4) NMOGCC (2)

LAA JNH ARM
NMOGCC