Form 9-331 (May 1963)			5. LEASE DESIGNATION AND SERIAL NO.		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			Joint Venture 6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache		
OIL GAS WELL X OTHER 2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME		
Palmer 0il & Gas Company 3. ADDRESS OF OPERATOR P. 0. Box 2564, Billings, Montana 59103			8. FARM OR LEASE NAME Apache - JVA 9. WELL NO.		
See also space 17	I (Manart logation also I - I - I - I - I - I - I - I - I - I	NO. 5 10. FIELD AND POOL, OR WILDCAT			
At surface 8	50' FNL, 1490' FEL	Blanco-Mesaverde 11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA			
14. PERMIT NO.	15. ELEVATIONS (Show whether	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		NW&NE& 29-27N-2W	
16.	7265' GR		Rio Arriba	New Mexico	
TEST WATER SHU FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	MULTIPLE COMPLETE ABANDON® CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Status Rep	REPAIRING W ALTERING CA ABANDONMEN	BING X	
Well was	OR COMPLETED OPERATIONS (Clearly state all perting of well is directionally drilled, give subsurface locally state all perting of well is directionally drilled, give subsurface locally state all perting of well is directionally drilled, give subsurface locally state all perting of well is directionally drilled, give subsurface locally state all perting of well is directionally drilled, give subsurface locally drill	ent details, and give pertinent dates, is cations and measured and true vertical	including estimated date depths for all markers	n.) of starting any and zones perti-	