

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		87 JUL 10 AM 11:03	3. LEASE DESIGNATION AND SERIAL NO. Jic. Contract #446
2. NAME OF OPERATOR Southland Royalty Co.		FARMINGTON RESOURCE AREA FARMINGTON, NEW MEXICO	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499			7. UNIT ASSIGNMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1840'S, 1000'E			8. FARM OR LEASE NAME Jicarilla 446
14. PERMIT NO.		15. ELEVATIONS (Show whether OF, RT, OR, etc.) 7027' GL	9. WELL NO. 1
			10. FIELD AND POOL, OR WILDCAT Choz Mesa Pic. Cliff
			11. SEC. T. R. M. OR BLK. AND SUBST OR AREA Sec. 8, T-27-N, R- 3-W N.M.P.M.
			12. COUNTY OR PARISH Rio Arriba
			13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDISE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

It is proposed to plug and abandon the subject well in the following manner:

MOL & RU. TOOH w/2 3/8" tbg. Check for bad joints.  
TIH w/2 3/8" tbg openended. Spot 150 sx (177 cf) @ 4010', w/25 sx (29 cf) to be squeezed into perforations and the remaining 125 sx (148 cf) to plug the 7" csg to 3340'  
Perforate 4 holes in 7" csg at 284', and squeeze w/45 sx (53 cf) inside 9 5/8" csg. to surface.  
Spot 10 sx (12 cf) at 50', to plug 7" casing to surface.  
Set dry hole marker. Rig down.  
Restore location.

RECEIVED  
JUL 10 1987  
C. W. BIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

*Peggy Oak*

TITLE Drilling Clerk

DATE

07-07-87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*John Keller*  
FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side