Form	9-331
Mav	1963)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on re-

SUBMIT IN TRIPLICATE.

Form approved.
Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SF 079107

GEOLOGICAL SURVEY							
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS		

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME WELL WELL X OTHER 2. NAME OF OPERATOR 8. FARM OR LEASE NAME Consolidated Oil & Gas, Inc. NCRA 9. WELL NO. 3. ADDRESS OF OPERATOR 1-E 10. FIELD AND POOL, OR WILDCAT

1860 Lincoln Street, Denver, Colorado 80295

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.

See also space 17 below.)

At surface

Blanco Mesaverde 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

1550' FNL & 1850' FEL

Sec. 22, T26N, R7W 12. COUNTY OR PARISH | 13. STATE

15. ELEVATIONS (Show whether DF. RT. GR. etc.) 14. PERMIT NO GL 6928'

Rio Arriba | New Mexico

TEST WATER SHUT-OFF FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

Lacer

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PULL OR ALTER CASING MULTIPLE COMPLETE

ABANDON* CHANGE PLANS

WATER SHUT-OFF FRACTURE TREATMENT

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING ABANDONMENT*

SHOOTING OR ACIDIZING (Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

11/7/79: Perf 5307-09-11-13-15-17-36-38-40-55-57-59-61 5406-08-10-87-89-5510-12 (20 holes - 0.32")

> Isolate perfs 5370-5550. Acidize with 100 gals. 15% NE and 300 gals. 15% NE.

11/8/79: Isolate perfs 5100-5380. Acidize with 100 gals. 15% NE and 500 gals. 15% NE.

> Set BP @ 5670. Frac with 53,000 gals. gelled fluid and 56,000 # 20-40 sand and 20,000 # 10-20 sand. press. 3400#, average press 2900# @ 42 BPM

18. I hereby certify that the foregoing is true and correct DATE ER 2.0 1980 1980 -TITLE Senior Production Engr. SIGNED OIL CON. COM. (This space for Federal of State office use) DIST. 3 APPROVED BY TITLE . CONDITIONS OF APPROVAL, IF ANY: