



**NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT**

**AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178 Fax (505) 334-6170**

**GARY E. JOHNSON  
GOVERNOR**

**JENNIFER A. SALISBURY  
CABINET SECRETARY**

January 26, 1996

Dolores Diaz  
Meridian Oil Inc  
PO Box 4289  
Farmington NM 87499

RE: Wells Which Require Retesting

Dear Dolores:

The 1995 Packer Leakage Tests on the following wells indicate communication between the producible zones:

SJ 27-4 Ut #105, G-19-27N-04W, 30-039-21012  
SJ 27-4 Ut #13A, O-20-27N-04W, 30-039-20983  
SJ 27-4 Ut #120, K-34-27N-04W, 30-039-22122  
SJ 27-5 Ut #24A, I-32-27N-05W, 30-039-22310  
SJ 27-5 Ut #8, L-32-27N-05W, 30-039-06806  
Reid A #1M, J-13-29N-10W, 30-045-24497  
Mexico Fed R #1, H-12-31N-13W, 30-045-22126  
Susco 16 State #1, M-16-32N-08W, 30-045-25278

To comply with Rule #112A, you are hereby directed to initiate remedial activity and retest the wells.

Sincerely,

Johnny Robinson  
Deputy O&G Inspector

JR/sh

cc: Well files