

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

CONTRACT 237

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

JICARILLA TRIBAL

7. UNIT AGREEMENT NAME

East Puerto Chiquito

8. FARM OR LEASE NAME MANCOS

9. WELL NO.

41 (F-20)

10. FIELD AND POOL, OR WILDCAT

Puerto Chiquito Mancos

11. SEC., T., R., M., OR S.E. AND
SURVEY OR AREA East

Sec. 20, T-27N, R-1E

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

BENSON-MONTIN-GREER DRILLING CORP.

3. ADDRESS OF OPERATOR

221 Petroleum Center Building, Farmington NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1900' FNL, 2008' FWL, Sec. 20, T-27N, R-1E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6998' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-13-81 Set Baker Model R packer at 4012'. Pressure tested bridge plug set at 4020'. Pressure held. Set packer at 3932'. Pressured up on perforations 3947' to 3984'. Reperforated 3970' to 3980' with 10 holes, 3948' to 3958' with 10 holes, 3885' to 3895' with 10 holes, 3898 to 3918' with 20 holes.

7-16-81 Acidized with 1000 gallons 15% HCL plus retarder and surfactant. Spotted acid down tubing and over perforations. Set packer. Pumped acid into formation. Pressures ranging from 1000# to 1600#. Inst. SIP 1000#. Opened tubing to flow back. Flowed back 16 barrels displacement water with blow of acid gas. Rigged up to swab.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Vice-President

DATE 1-20-81

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

BY