



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONEY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

June 24, 1986

Ms. Kay Eckstein
Columbus Energy Corp.
P.O. Box 2038
Farmington, NM 87499

Re: Champlin #1E J-35-27N-04W

Dear Kay:

The annual packer leakage test on the referenced well was inconclusive in proving zone separation.

Please reschedule and retest the well in such a manner as to prove zone separation. Shut in both zones for a minimum of 3 days. Blow the higher pressured zone to the atmosphere, or through a separator to a storage tank for as long as it takes to get a significant drop.

Please advise this office at least 24 hours prior to test, so we may provide a witness.

Yours truly,

A handwritten signature in cursive script, reading "Charles Gholson".

Charles Gholson
Oil & Gas Inspector

CG/dj

xc: Well File