Form 3160-5 (August 1999)

UNITED STATES

FORM APPROVED OMB NO. 1004-0135

DEPARTMENT OF THE INTERIOR					Expires: November 30, 2000		
BUREAU OF LAND MANAGEMENT					5. Lease Serial No. SF-079391		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to receive an					6. If Indian, Allottee of	- T-iho Nomo	
abandoned we	II. Use form 3160-3 (AP	D) for such pro	NOV 2	101 S	6. If Indian, Allottee C	if Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on Peverse RECEIVED					7. If Unit or CA/Agreement, Name and/or No. SAN JUAN 27-5 UNI		
1. Type of Well ☐ Other ☐ Other				DIST. 3 SANJUAN 27-5 UNIT 69M			
2. Name of Operator BURLINGTON RESOURCES	PEGGY CONE E-Mail: pbradin	Mager-inc.co		9. API Well No. 30-039-23823			
3a. Address 3401 EAST 30TH FARMINGTON, NM 87402	3b. Phone No. (include accords) Ph: 505.326.9727 Fx: 505.326.9563			10. Field and Pool, or Exploratory BLANCO MV/BASIN DK			
4. Location of Well (Footage, Sec., 7)			11. County or Parish, and State			
Sec 7 T27N R5W Mer NESE				RIO ARRIBA COUNTY, NM			
12. CHECK APP	ROPRIATE BOX(ES) To	O INDICATE N	ATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
	☐ Acidize	☐ Deeper		☐ Production (Start/Resume)		■ Water Shut-Off	•
☐ Notice of Intent	☐ Alter Casing	☐ Fractur	e Treat	☐ Reclamation		■ Well Integrity	
Subsequent Report ■ Subsequent Report Subsequent Report	Subsequent Report		☐ New Construction ☐ Reco		ete	☑ SUBCOM	
☐ Final Abandonment Notice ☐ Change Plans		☐ Plug an	☐ Plug and Abandon ☐ Temporarily Abandon		rily Abandon		
☐ Convert to Injection		☐ Plug Back ☐ Water Disposal					
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 7-26-01 MIRU. SDON. 7-27-01 ND WH. NU BOP. TIH, tag up. TOOH w/178 jts 1 1/2" Mesaverde tbg. TIH, blow well & CO to top of pkr @ 5980'. TOOH. Work seal assembly looses. SDON. 7-28-01 TOOH w/168 jts 2 3/8" tbg & seal assembly. TIH w/retrieving tool. TOOH. SDON. 7-29-01 TIH w/6 1/4" mill. Establish circ. Mill through top of Inr. TOOH w/mill. TIH w/retrieving tool. Latch pkr @ 5957'. Establish circ. TOOH w/pkr & tools. SDON. 7-30-01 TIH, ran CCL-GR @ 4600-5000'. TOOH. TIH w/7" RBP, set @ 4900'. Dump 100# frac sd on RBP. Load hole w/2% KCl wtr. Ran CBL-CCL-GR @ 3400-4900', TOC @ 3536' (top of Inr). TOOH. TIH w/9 5/8" pkr, set @ 62'. PT RBP & csg to 3000 psi/10 min, OK. TOOH. TIH, perf Lewis w/1 SPF @ 3970, 3980, 3985, 3995, 4198, 4345, 4350, 4370, 4375, 4380, 4385, 4390, 4400, 4425, 4430, 4510, 4515, 4520, 4525, 4530, 4535, 4540, 4575, 4580, 4615, 4650, 4660, 4763, 4840, 4855' w/30 0.3" diameter holes total. Acidize w/1260 gal 15% HCl. Frac Lewis w/1059 bbl 20# linear gel, 200,000# 20/40 Brady sd. CO after frac. 7-31-01 Blow well & CO.							
14. I hereby certify that the foregoing in Name (Printed/Typed) PEGGY (& GAS, sent to by Lucy Bea	I Information S to the Farming on 08/13/2001 RT AUTHORIZE	ton ()		-		
Signature Date 08/07/2001							
Signature	THIS SPACE F				<u> </u>		
		 	<u> </u>				
_Approved By		Title		Date			
Conditions of approval, if any, are attached. Approval of this notice does not vectify that the applicant holds legal or equitable title to those rights in the subjection would entitle the applicant to conduct operations thereon.			Office		ACCEPTED	FOR RECORD	_

** ORIGINAL **

Additional data for EC transaction #5261 that would not fit on the form

32. Additional remarks, continued

8-1-01 Blow well & CO. TOOH. TIH w/notched collar to 4803'. Establish circ. Circ hole clean to 4900'. 8-2-01 TOOH. TIH w/retrieving tool. Establish circ. Circ hole clean. 8-3-01 Circ hole clean. Release RBP, TOOH. TIH. Establish circ. Circ hole clean to PBTD @ 7813'.

8-4/5-01 Circ hole clean.

8-6-01 Circ hole clean. TOOH. TIH w/236 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 7767'. (SN @ 7736'). ND BOP. NU WH. RD. Rig released.

Well will produce as a Mesaverde/Dakota commingle under R-11363