

Apache 27-2-28 #1

I-28-27N-02W

RICHMOND PETROLEUM, INC.

01-22-91

30-039-25044

B.H. 1915/S; 1915/E
 F. Loc. 500/S; 500/E
 Elev. 7315 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____ T Gas
 Prod. Stim. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. T. _____ @ _____ T Gas
 Csg. Perf. _____ Grav. _____ 1st Del. Gas _____
 1st Del. Oil _____

I.P.	BO/D MCF/D After	Hrs.	SICP	PSI After	Days GOR	TEST DATA						Ref. No.
						Schd.	PC	Q	PW	PD	D	
	TOPS			X								
Ojo Alamo			C-103			Well Log						
Kirtland			C-104			Plat	X					
Fruitland						Electric Log						
Pictured Cliffs						C-122						
Chacra						Dfa						
Cliff House						Dac						
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrada												

R-9419

Acres 430.56

P
 o
 o
 I Gavilan Mar. Co. RA S 28 T 27N R 02W U I Oper. Richmond Petroleum Loc. Apache 27-2-28 No. 1



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO
701-90-0001 (WC)
3162.3-1.0 (019)

FEB. 28 1992

RECEIVED

MAR 2 1992

OIL CON. DIV.]
DIST. 3

Richmond Petroleum Inc.
2651 N. Harwood, Suite 500
Dallas, Texas 75201

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 1 Apache 27-2W-28, Sec. 28, T. 27 N, R. 2 W, Rio Arriba County, New Mexico, lease 701-90-0001. The subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

1 Enclosure

cc:
New Mexico Oil Conservation Division, Aztec, NM
BIA, Dulce

ABANDONED LOC