Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

Expires: November 30, 20

5. Lease Serial No. Jic. Cont. 95

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

abandoned well. Use For				Jicarilla /	Apache
SUBMIT IN TRIPLICATE - Other instructions or reverse side 2001				7. If Unit or CA/Agreement, Name and/or N 21289	
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator ENERGEN RESOURCES CORPORATION 3a. Address		3b. Phone No. (include area cod	le)	8. Well Name Jicarilla ! 9. API Well N 30-039-265	95 3C
2198 Bloomfield Highway, Farmington 4. Location of Well (Footage, Sec., T., R., M., or Survey I 2340' FNL, 990' FWL, Sec. 35, T27N,	Description)	7148 Audio 1			ool, or Exploratory Area
	1			11. County or Rio Arriba	
12. CHECK APPROPRIATE	BOX(ES) TO IN	DICATE NATURE OF NOTICE	CE, REP	ORT, OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent Subsequent Report	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamatio	(Start/Resume)	Water Shut-Off Well Integrity
Final Abandonment Notice	Casing Repair Change Plans Convert to Inject	New Construction Plug and Abandon Plug Back	Recomplete Temporaril Water Disp	ily Abandon Add MV	
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2					

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

It is intended to Add the Mesa Verde as follows:

- 1. MIRU. TOH with tubing
- 2. Set CIBP at 7200'. Pressure test casing to 3500 psi.
- 3. Selectively perforate the Mesa Verde from 5637-6160'. Fracture treat interval
- 4. TIH and clean out with air mist.
- 5. Land tubing at 6150' Return to production

Note: It is intended to downhole commingle the MV and Gallup at a later date

Title
Production Assistant
Date 9/20/01
FOR FEDERAL OR STATE OFFICE USE
TitleLands and Mineral Resources Date OCT 1 20th
e does not warrant or office ts in the subject lease
ntic