Submit 3 Copies To Appropriate District	State of New Mexico					Form C-103 Revised March 25, 1999		
Office District I	Energy, Minerals & Natural Resources			WELL API	NO.	Kevised N	narch 25,	1999
District I 1625 N. French Dr. Hobbs, NM 88240	OII COMORDIA	ATION DIV	CION				9-26566	
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION 2040 South Pacheco			5. Indicate	e Type o STATE	f Lease	FEE 🗀	
District III						لتتا		
1000 Rio Brazos Rd., Aztec,NM 87410	Santa Fe,	NM 87505		6. State O	il & Gas	Lease No).	
District IV 2040 South Pacheco,Santa Fe,NM 87505						TATE		
SUNDRY NO	TICES AND REPORTS	ON WELLS	DV TVO A	7. Lease Na	ame or Ur	nit Agreeme	nt Name	
(DO NOT USE THIS FORM FOR PE DIFFERENT RESERVOIR. USE"AL	ROPOSALS TO DRILL OR TO DE PPLICATION FOR PERMIT" (FOR	epen or plug bad M C-101) for s uc	CK TO A					
PROPOSALS.)		15/16/1	1970					
1. Type of Well:	. C X T	(3) II	4 73	RINCON UNIT				
Oil Well Gas Well 2. Name of Operator	Other Other	A RE	300-	8. Well No.				
2. Name of Operator	PURE RESOURCES L.P.	ON CE	IVE 3			156M		
3. Address of Operator		O OB	On S	9. Pool name or Wildcat				
P.O. BO	X 850 , BLOOMFIELD, NM	87413 7.5		<u> </u>	<u> </u>	lesa Verde		
	: 1956' feet from	the South - 1	ine and	845'	feet for	n the	East	line
Unit Letter	. 1730 leet Holli				_			
Section	16 Township			_NMPM _	RIO A	RRIBA	County	
	10. Elevation (Sho	w wheather DF,RI	(B,RT,GR,etc.)					
		6490' G		Oth on D				
11. Check A	Appropriate Box to Indica INTENTION TO:	te Nature of Not	ice, Report, C	SEQUEN	aca T RFP(ORT OF:		
NOTICE OF		<u> </u>			_		0.4.00.1.5	_
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEC	IAL WORK		لــا	ALTERING (CASING	لـا
TEMPORARILY ABANDON	CHANGE PLANS	СОММІ	ENCE DRILLING	OPNS	PLUG AND			
-	─ '` MULTIPLE	CASING	S TEST AND	ABANDONMENT				
PULL OR ALTER CASING	COMPLETION	CEMEN						
OTHER:			:	Cor	nplete M	v		_ 🗶
12. Describe proposed or compl	eted operations (Clearly sta	ate all pertinent	letails, and gi	ve pertinen	t dates, i	ncluding e	estimated	date
of starting any proposed wo	rk. SEE RULE 1103. For	Multiple Compl	etions: Attac	h wellbore	diagram	of propos	ed compl	etion
or recompliation		1 - 4			-		-	
•								
	Cat Deldas Diva	MEE20' to toot	Maca Vard	a Zone				
Set Bridge Plug @5520' to test Mesa Verde Zone See Attached								
See Allaciicu								
I hereby certify that the information	on above is true and complete	to the best of my	knowledge and	l belief.				
	1	. to the seat of my	5.J.	Basin Area				
SIGNATURE 7/4 7	Mily	TITLE _	Drilling/Pro	duction For	eman	_DATE _	11/14/	01
Type or print name	Mi	cheal C. Phillips			TELI	EPHONE NO.	(505) 6	<u>32-181</u> 1
This space for State Use)			PUTY OIL &	SAS INSPEC	TOR. PIST	A NIO	V 1 0	202:
* DDDOVED DV	ened by Oharle T. Park	n Title			-	DATE	w y o	490 1
APPROVED BY		نابا ۱۱۱				<i></i> _		

APPROVED BY

Conditions of approval, if any:



Pure Resources, Inc. Well History RINCON UNIT #156M Complete Mesa Verde Zones

10/15/01

MIRU KEY #65; TALLY OUT OF HOLE WITH 241 JTS OF 2 3/8" TBG

10/17/01

RU SCHLUMBERGER WIRELINE; SET EASYDRILL BRIDGE PLUG @ 5520'; PRESSURE TEST TO 1200#; PERFORATE POINT LOOKOUT FORMATION AS FOLLOWS: 5374', 76', 78', 84', 90', 92', 96', 5404', 06', 08', 12', 14', 16', 18', 20', 24', 35', 39', 43', 47', 55', 64', 68', 73';

10/18/01

RU BJ TO ACIDIZE FORMATION; WELL BROKE DOWN AT 3080#; ACIDIZE AND BALL OFF PERFS WITH GOOD BALL ACTION

10/22/01

DRILL OUT BRIDGE PLUG AT 5320'; CLEAN OUT TO 5520'; TOH TO TOP OF PERFS; .

10/25/01

RU BJ; FRAC POINT LOOKOUT WITH 39,185 GALS 70Q FOAM WITH 91,755# BROWN SAND 20/40 AND 4320# FLEXSAND 14/40 MESH IN 5 STAGES; AVG PRESS 2198#, MAX PRESS OF 2287#; ISDP OF 229#; RU SCHLUMBERGER; RAN AND SET BRIDGE PLUG AT 5335"; PRESS TEST RIG PUMP TO 1200#; PERF CLIFF HOUSE FORMATION AS FOLLOW: 4855', 61', 65', 70', 79', 81', 83', 4902', 04', 06', 10', 14', 16', 18', 28', 30', 34', 36', 41', 45', 53', 57', 68', 72', 5138', 42', 46', 50', 5213', 20', 26', 34', 38' (TOTAL OF 33 HOLES); RU BJ; BROKE FORMATION DOWN AT 15 BPM; ACIDIZE PERFORATIONS WITH GOOD BALL ACTION; RU SCHLUMBERGER; RETRIEVE BALL SEALERS; RU BJ; FRAC CLIFF HOUSE WITH 49,049 GALS 70Q FOAM WITH 122,625# BROWN SAND 20/40 AND 6240# FLEXSAND; AVG PRESS 3327#, MAX PRESS 3421#, ISDP OF 1851#, 5 MIN 1732#, 10 MIN 1700#, 15 MIN 1668#; OPEN WELL UP TO BLOW PIT AFTER 1 HR OF SHUT IN WITH 1275# ON 8/64" CK; LEFT WELL FLOWING WITH FLOW BACK CREW ON LOCATION.

10/26/01

TIH W/3 7/8" MILL, STAGING AIR AND FOAM TO 5335'; DRILL OUT BRIDGE PLUG AND CLEAN OUT TO 5500'; PLUG MILL;

11/3/01

MESA VERDE ONLY; WELL IS FLOWING UP CASING; NO TUBING IN WELL.

