

Submit 3 Copies to Appropriate District Office
3 NMOCDD
1 File
1 WBU wios
DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88270
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-045-05595
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-9707
7. Lease Name or Unit Agreement Name West Bisti Unit
8. Well No. 158
9. Pool name or Wildcat Bisti Lower Gallup
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6288' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Dugan Production Corp.
3. Address of Operator P.O. Box 420, Farmington, NM 87499	4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 36 Township 26N Range 13W NMPM San Juan County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug by setting Class B + 6% gel plugs as follows:

1. 100' plug across Gallup top @ 4695'.
2. Perforate 50" below Mesa Verde top @ 1960' and spot 100' plug inside and outside casing.
3. Perforate 50" below Pictured Cliffs top @ 1210 and spot plug inside and outside casing to cover Fruitland top @ 895'.
4. Perforate 50" below surface casing @ 212' and circulate cement to surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John Alexander TITLE Operations Manager DATE 6/30/92
TYPE OR PRINT NAME John Alexander TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Original Signed by CHARLES CHILSON TITLE _____ DATE JUN 30 1992
CONDITIONS OF APPROVAL, IF ANY: _____