Form 9-531 (May 1963)

14. PERMIT NO.

16.

## SUBMIT IN TRIPLICATIO UNITED STATES DEPARTMENT OF THE INTERIOR verse side)

Form approved. Budget Burenu No. 42 401424. 5. LEASE DESIGNATION AND MURIAL NO.

G. IF INDIAN, ALLOTTED OR TRIBE NAME.

GEOLOGICAL SURVEY

	<del></del>					
VICINITY	NOTICES	V ND	REPORTS	ON	WFII	ς

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.)

XJOTHER WELL 2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR 87401 DOT 4 P. O. Box 990, Farmington, New Mexico 4. LOCATION OF WELL (Report location clearly and in accordance with any State regularments.

See also space 17 below.)

COM.

At surface

1404'S, 1142'E

DIST. 3

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

McManus 9. WELL NO.

NM 04226

10. FIELD AND POOL, OR WILDCAT

Ballard Pictured Cliffs 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 31, T-26-N, T-8-W, N.M.P.M.

12. COUNTY OR PARISH | 13. STATE

U. T. S. C. T. A. S. S.

San Juan New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6408' GL

			•			
NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other)  (Note: Report results of my Completion or Recompletion	REFAIRING WELL ALTERING CASING ABANDONMENT*  Liftiple completion on Well Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The subject well was plugged and abandoned during the following dates 09-15-76 to 09-20-76.

- 1. Spot 25 sk cement plug from 1879-2095'. (Pictured Cliffs top 2022')
- Perforate squeeze hole 1372'. Spot 45 sk cement plug squeeze 20 sks through perfs. (Plug from 1172-1372')
- Shot off casing at 1033', recover, spot 60 sk plug. (823-1033') 3.
- Spot 30 sk cement plug (75-175') base of surface scg. at 95'.
- Placed a 10 sk cement plug at the surface installed dry hole marker, cleaned up 5. location.

Note: A final subsequent report will be filed after the production equipment has been removed and surface restoration is complete.

18. I hereby certify that the foregoing is true and correct	:				
SIGNED D. Brisco		Drilling Clerk	DAT	September	<u>29, 1</u> 970
(This space for Federal or State office use)	, , , , , , , , , , , , , , , , , , , ,		1		g S
APPROVED BY	TITLE		FAG:	<u> 30 1976 </u>	