# State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	orts on Wel/1s
	<b>API # (assigned by OCD)</b> 30-045-05628
Type of Well GAS	5. <b>Lease Number</b> E-8248-2
GAD	6. State Oil&Gas Lease #
	E-8248-2 7. Lease Name/Unit Name
. Name of Operator  MERIDIAN OIL	•
	State A Com 8. <b>Well No</b> .
. Address & Phone No. of Operator	2
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. <b>Pool Name or Wildcat</b> Ballard Pictured Clif
. Location of Well, Footage, Sec., T, R, M	10. Elevation: 6462 GR
1400'FNL, 1400'FEL, Sec.32, T-26-N, R-8-W, NMPM, San Ju	an County
Type of Submission Type of Action	
X Notice of Intent Abandonment C	Change of Plans
Recompletion N	New Construction
Subsequent Report Plugging Back N Casing Repair W	Non-Routine Fracturing Nater Shut off
Final Abandonment X Altering Casing C	
X_ Other - Stimulate	
3. Describe Proposed or Completed Operations	
It is intended to squeeze cement behind the 5 1/2" of casing, cement to surface, perforate and fra open hole completion per the attached proced	cture treat this Pictured Cliffs
REVISED  It is intended to squeeze cement behind the 5 1/2" of casing, cement to surface, perforate and fra	cture treat this Pictured Cliffs
REVISED  It is intended to squeeze cement behind the 5 1/2" of casing, cement to surface, perforate and fra	cture treat this Pictured Cliffs
REVISED  It is intended to squeeze cement behind the 5 1/2" of casing, cement to surface, perforate and fra	cture treat this Pictured Cliffs ure and wellbore diagram.
REVISED  It is intended to squeeze cement behind the 5 1/2" of casing, cement to surface, perforate and fra	cture treat this Pictured Cliffs
REVISED  It is intended to squeeze cement behind the 5 1/2" of casing, cement to surface, perforate and fra	cture treat this Pictured Cliffs ure and wellbore diagram.
REVISED  It is intended to squeeze cement behind the 5 1/2" of casing, cement to surface, perforate and fra	DECEMBER  APR - 8 9865
REVISED  It is intended to squeeze cement behind the 5 1/2" of casing, cement to surface, perforate and frate open hole completion per the attached proced.	DECENTED  APR - 8 3835  OUL COME DIVE
It is intended to squeeze cement behind the 5 1/2" of casing, cement to surface, perforate and frate open hole completion per the attached proced	DECENTED  APR - 9 985  OUL COMO DEVA  DISTO 3

### STATE A COM #2 PC Pictured Cliffs Refrac G 32 26 8 San Juan County, N.M.

#### Revised 4/5/95

- Comply to all NMOCD, BLM, & MOI rules & regulations. MOL and RU completion rig. NU 6" 900 series BOP W/offset rams, flow tee and stripping head. NU blooie line and 2-7/8" relief line.
- 2. TOH w/1" tbg & lay down. Set 5-1/2" retrievable BP @ 1300' on wireline & top w/2 sx sand.
- 3. Perf 2 sq holes @ 1145' (50' below top Ojo Alamo). Run 5-1/2" pkr on 2-3/8" work string & set @ 800'. Establish rate & sq w/22 sx cmt. This will cover 50' above and below the Ojo Alamo behind the 5-1/2" csg w/50% excess. If circ is obtained out bradenhead valve, continue pumping & circ cmt (about 168 sx).
- 4. If circ was not obtained, perf 2 sq holes @ 149' (50' below surface csg shoe) & circ cmt out bradenhead valve. WOC.
- 5. TIH w/4-3/4" bit on 2-3/8" tbg & drill & C.O. cmt to ret BP. TOH.
- 6. TIH w/retrieving head & retrieve RBP @ 1300'. TOH.

  TIH w/4-3/4" bit on 2-3/8" & C.O. w/air/mist to TD 2210'. TOH.
- 7. Load hole w/500 gal 1% KCL water. Run an advanced integrated data processing GSL neutron log 2210'-1700. Correlate log to open hole Electric logs from offset wells.
- 8. Run 3-1/2"-OD 9.2# J-55 NUE tbg to TD 2210' w/Omega type locking collar above 2' tbg sub w/Texas guide shoe on bottom. Cement w/100 sx 50-50 Cl "B" POZ w/2% gel & 6-1/2#/sx kolite and 10% salt and 2% Cacl. (Yield=1.44 cf/sx). After cmt, run 2 wiper balls & Omega wiper latching plug, followed by 100 gal 7-1/2% HCL acid. Space out using tbg subs & install 3-1/2" csg in new csg spool. Install 5000 psi rental frac valve on 3-1/2" csg.
- 9. Role hole w/1% KCL water. Run GR-CCL & coorelate to neutron log. Perf about 50' of PC interval as per Production Engrineering Dept. Perf using 2-1/8" formed wire w/ 22 gr #307 Owen charges which make a 0.38" hole and have 20.73" of penetration.

### STATE A COM #2 PC - PC WORKOVER Page 2

- 10. Break down PC perfs down 3-1/2" csq w/2500 gal 15% HCL and 150% excess perf balls. Acidize @ 7 BPM w/ max pressure = 6000 psi. Run junk basket to retrieve balls.
- 11. Spot and fill 2 400 bbl. frac tanks with 2% KCL water. Filter all water to 25 microns. One tank is for gel & one tank is for breakdown water. Usable gel water required for frac is 240 bbls.
- 12. Frac Pictured Cliffs down 3-1/2" csg w/33,000 gals. of 70 quality foam using 30# gel as the base fluid & 60,000# 20/40 Arizona sand. Pump at 40 BPM. Monitor bottomhole and surface treating pressures, rate, foam quality, & sand concentration with computer van. Sand to be tagged with 0.4 mCi/1000# Ir-192 tracer. Max. pressure is 6000 psi and estimated treating pressure is 3000 psi. Treat per the following schedule:

	Foam Vol.	Gel Vol.	Sand Vol.
<u>Stage</u>	(Gals.)	<u>(Gals.)</u>	<u> (lbs.)</u>
Pad	8,000	2,400	
1.0 ppg	5,000	1,500	5,000
2.0 ppg	10,000	3,000	20,000
3.0 ppg	5,000	1,500	15,000
4.0 ppg	5,000	1,500	20,000
Flush	( 712)	( 214)	
Totals	33,000	9,900	60,000#

Treat frac fluid with the following additives per 1000 gallons:

- \* 30# J-48 (Gel)
- \* 1.0 gal. Aqua Flow (Non-ionic Surfactant)
- \* 1.0# GVW3 (Enzyme Breaker)
- \* 1.0# B-5 (Breaker)
- \* 5.0 gal Fracfoam I (Foamer) \* 0.38# FracCide 20 (Bacteria \* 0.38# FracCide 20 (Bacterialcide)

Shut well in after frac for six hours to allow the gel to break.

- 13. Open well through choke manifold and monitor flow. Flow @ 20 bbl/hr, or less if sand is observed. Take pitot gauges when possible.
- 14. Change out frac valve w/tbg head. TIH w/notched collar on 1-1/4" IJ tbg & C.O. to 2205'. Monitor gas and water returns and take pitot gauges when possible.
- 15. When wellbore is sufficiently clean, TOH and run after frac gamma-ray log from 2205'-1700'.
- 16. TIH with 1-1/4" IJ tbg w/SN one jt above open ended bottom and again cleanout to 2205' (use expendable check, if necessary). When wellbore

## STATE A COM #2 PC - PC WORKOVER Page 3

17. Repair or replace any bad wellhead valves and connections. ND BOP and NU wellhead & tree. Rig down & release rig.

Approve:		
	Drilling	Superintendent

**VENDORS:** 

Wireline: Blue Jet 325-5584
Frac & Cmt: Howco 325-3575
RA Tagging: Pro-Technics 326-7133

PMP

### Pertinent Data Sheet - STATE A COM #2 PC

Location: 1400'FNL 1400' FEL SEC. 32 T26N R08W, SAN JUAN COUNTY, N.M.

Field: Ballard Pictured Cliffs Elevation: 6462' TD: 2200'

PBTD: 2200'

<u>Prop#:</u> 012657900 <u>Lease:</u> State E-8248

DP#: 50994A GWI: 97.50% NRT: 84.19%

<u>Completed:</u> 12-6-55 <u>NRI:</u> 84.19%

### <u>Initial Potential:</u>

Gauge: 2122 MCF/D, SIP: 609 PSI

Casing Record:

<u> Hole Size</u>	<u>Csg. Size</u>	Wt. & Grade	Depth Set	Cement	Top/Cmt
12-3/4"	8-5/8"	24# J-55	991	80 sx	N/A
7-7/8"	5-1/2"	14# J-55	2128'	100 sx	1617'@ 75% EFF.

<u>Tubing Record:</u> 1" 1.7# 2153'

Formation Tops:

Ojo Alamo 1095' (Ernie Bush)

Pictured Cliffs 2123'

Logging Record: No Logs in Section

Stimulation: Fraced Open Hole @ 2128'-2200'w/30,000# sand in oil.

Workover History: NONE

<u>Production History:</u> PC cumulative = 738 MMCF. Current Capacity= 27 MCF/D.

Pipeline: EPNG

PMP

### STATE A COM #2 PC

UNIT G SECTION 32 T26N R8W SAN JUAN COUNTY, NEW MEXICO

