

				X
		33		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078156
Unit Gov't Salge

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
To Sandfrac	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October, 13, 1958

Well No. B-5 is located 660 ft. from (N) line and 660 ft. from (E) line of sec. 33


C NE NE 33 26N 13W New Mexico PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Bisti-Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation ~~of the derrick floor~~ above sea level is 6288 ft. GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is proposed to clean out to 5100' KB. Set Baker CI Bridge Plug @ 5022' KB. Sandfrac w/30,000# sand and 450 gals Dowell J-90 fluid loss additive in 30,000 gals of lease crude, dropping 30 nylon core balls after 15,000 gallons. Swab csg clean, drill out bridge plug, and run tubing and rods and place on production.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company

Address Box 180

Denver 1

Colorado

By _____

Title District Superintendent