

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a sufficient reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER Salt Water Disposal

2. NAME OF OPERATOR
Texaco Inc.

3. ADDRESS OF OPERATOR
P.O. Box EE, Cortez, CO. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FSL & 2130' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether of, or in, RESOURCE AREA)
5732' KB

5. LEASE DESIGNATION AND SERIAL NO.
14-20-0603-8104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Navajo Tribe "AL"

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
Tocito Dome

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 28, T26N, R18W NWPM

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

JUL 18 1985
OIL CON. DIV. 1
DIST. 3
RECEIVED
JUL 15 1985

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco Inc. proposes to P & A This well because it is uneconomical to produce. The well was shut-in in May, 1982. Cumulative production is 5729 BO and 18266 MCF Gas. Well to be plugged and abandoned contingent of approval by Texaco's management (Approximately 90 days.)

ABANDONMENT PROCEDURE:

- 1.) Fill hole w/mud.
- 2.) Spot 10 sx cement plug across Barker Creek perms.
- 3.) Spot 10 sx cement plug @ 5700'
- 4.) Perf 4-way squeeze shot @ 4950' and squeeze w/30 sxs cement. (Leave 8 sx cement inside 4 1/2" csg.)
- 5.) Perf 4-way squeeze shot @ 3850' and squeeze w/30 sxs cement. (Leave 8 sx cement inside 4 1/2" csg.)
- 6.) Perf 4-way squeeze shot @ 2135', and squeeze w/30 sxs cement. (Leave 8 sx cement inside 4 1/2" csg.)
- 7.) Perf 4-way squeeze shot @ 1560', and squeeze w/30 sxs cement. (Leave 8 sx cement inside 4 1/2" casing.)
- 8.) Perf 4-way squeeze shot @ 750' and squeeze w/30 sxs cement. (Leave 8 sx cement inside 4 1/2" csg.)
- 9.) Spot 4 sx surface plug inside 4 1/2" csg, and 10.5 sx surface plug between 4 1/2" and 8 5/8" csg.
- 10.) Erect dry hole marker and clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Area Superintendent DATE 7/9/85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:
BLM (6) - NMOGCC (3) - JNH-AJS - ARM-Navajo Tribe

APPROVED
JUL 17 1985
[Signature]
AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

NMOGCC