


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **078091**
Unit **Gov. Bouthit**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	Report of running production string casing

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 4, 1956


Gov. Bouthit
Well No. **B-5** is located **2920** ft. from **XXX** [S] line and **1930** ft. from **XX** [W] line of sec. **29**
N.E. 1/4, Sec 29 (1/4 Sec. and Sec. No.) **26 N** (Twp.) **13 W** (Range) **N.M.** (Meridian)
Histi-Gallup (Field) **San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **6534** ft. **GL**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 8-7/8" hole to 5393' KB. Completed logs, conditioned hole and run 5 1/2" 15.9# Casing equipped with Baker Float Collar and Shoe, landed at 5397' KB and cemented with 100 sac regular 3/4 Gal cement. Displaced cement to 5399' KB. Float held 64. Pen temperature survey and found top of cement behind casing at 4730' KB.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The British-American Oil Producing Company**

Address **Box 100**

Denver 1, Colorado

Original Signed by:
Thomas M. Hegan
By **Thomas M. Hegan**
Title **District Superintendent**

1. The first step in the process of the investigation is the identification of the problem. This is done by the investigator who is responsible for the study. The investigator must first identify the problem that is being investigated. This is done by the investigator who is responsible for the study. The investigator must first identify the problem that is being investigated.

