

TONEY ANAYA

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

March 27, 1986

Mr. B.D. Shaw Amoco Production Co. 501 Airport Dr. Farmington, NM 87401

Re: Navajo Tribal N #2, G-20-26N-18W Navajo Tribal U #1, L-21-26N-18W USG Section 19 #17, I-19-29N-16W

Dear Mr. Shaw:

A letter from this office, dated November 18, 1985, directed you to repair casing or packer leaks on the referenced wells within 60 days. To date we have not received any sundry notices showing intent to repair the casing. A letter from this office, dated October 23, 1981, directed you to repair a packer or tubing leak on the USG Section 19 #17. To date we have not received any report of that repair. Additionally, the names on the well signs do not correspond to the well names listed in our records. In order to comply with NMOCD Rule 1104, it will be necessary to file Division forms C-104, showing change of well name, immediately.

You are hereby directed to initiate remedial action to repair the referenced wells within 30 days.

Yours truly,

Carolyn J. Taplin

Deputy Oil & Gas Inspector

xc: Prentiss Childs

UIC File

Operator File

Carolyn to

₩ell Files

BLM