DECEIVED	U wios xc: Navajo EPA (Jim Walker).	- Shiprock
OUL COMO DEPARTME OUNCE DE LA COMO DEL COMO DE LA COMO DEL LA COMO DE LA COM	ITED STATES INT OF THE INTERIOR LAND MANAGEMENT S AND REPORTS ON WELLS If III or to deepen or reentry to a different reservoir. OR PERMIT—" for such proposals	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM 013492 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
I. Type of Well		West Bisti Unit
Oil Gas Well Other *Water Injection Well P&A 2. Name of Operator		8. Well Name and No. West Bisti Unit 113
Dugan Production Corp. 3. Address and Telephone No.		9. API Well No. 30-045-05749
P.O. Box 420, Farmington, NM 87499 (505) 325-1821		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		* Bisti Lower Gallup
1980' FSL - 1980' FEL		11. County or Parish, State
Sec. 19, T26N, R13W, NMPM		San Juan, NM
	s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	A bandonment	Change of Plans
Subsequent Report	Recompletion Plugging Back	New Construction Non-Routine Fracturing
Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off
	Other	Conversion to Injection Dispose Water
	pertinent details, and give pertinent dates, including estimated date of starting	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Law form)
Plugged well as follows: 1. Pulled tubing. Found parts ±3816'. Received permiss 2. Ran 5½" cement retainer a Pulled tubing. BLM repre 3. Perforate 5½" casing @ 37 4. Spot 54 cu. ft. class MBM Verde 3600' - 3750'. 5. Perforate 5½" casing @ 25 6. Spot 60 cu. ft. class MBM 7. Perforate 5½" casing @ 16 8. Spot 177 cu. ft. class MBM Cliffs plug 1310' - 1675' 9. Perforate 5½ casing @ 499 Job complete 11/8/95.	ed at 3801. Ran overshot & bumper sub. Recovered ±10 ion from Steve Mason (BLM) to set retainer above fis and set @ 3773. Unable to pump through retainer. sentative (Belva Christensen) gave permission to alt 50. cement at 3770. Displace cement to 3600. Plug to 051. cement at 2520. Displace cement to 2300. Mesa Ve 75.	5' fish. Left top of fish sh. Pressure up to 700 psi. er procedure. separate Gallup from Mesa erde plug 2300' - 2520'.
I hereby certify that the foregoing is true and correct Signed Ohn Chandle	Operations Non-	
(This space for Federal or State office use)	Tide Operations Manager	Date
Approved by	Title	PROVED
······································		AN 2