Form	
(Feb	. 1961)

	0	

## (SUBMIT IN TRIPLICATE)

UNITED STATES	
DEPARTMENT OF THE INTERIOR	Uı
GEOLOGICAL SURVEY	

Land Office	New	Mexico
	0290	
Onit		

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF IN			SUBSEQUENT REPORT OF WATER SHUT-OFF	X
1	TENTION TO CHANGE P		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	1
I NOTICE OF IN		ER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
		OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	1
NOTICE OF IN	TENTION TO SHOOT OF	ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF IN	TENTION TO PULL OR	ALITER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF IN	TENTION TO ABANDON	WELL		
	(INDICA	TE ABOVE BY CHECK MARK	NATURE OF REPORT, NOTICE, OR OTHER DATA)	
			December 1	19 60
onsolida	ted - Hale			, 1/
Well No.	1=24 is locat	ted 795 ft. from	${N \choose N}$ line and 1700 ft. from ${E \choose N}$ line of se	c. 24
NE	24	26N	BN ING-M	
8ec. Basin Da	and Sec. No.)	(Twp.) ( S <b>an Juan</b>	Range) (Meridian)	
	(Field)		Subdivision) (State or Territory)	
Ballard	P.C.	floor above sea lev	4000	
State names of	and expected depths to	objective sands; show size	LS OF WORK  s, weights, and lengths of proposed casings; indicate mudding	jobs, cement
State names of	and expected deprine to	ing points, and all ot	her important proposed work)	
			int important proportion work,	
Drilled 8 Cemented the control of th	thru shoe wit Cemented thi	h 398 sacks 6%	" 15.5# & 14# J=55 casing to 7240' gel cement, bumped plug with 3000 at 2806' with 150 sacks 6% gel cem	psi -
Cemented held OK. bumped plumped plump	thru shoe wit Cemented thr ug with 3000	th 398 sacks 6% tu stage collar psi - held OK.	" 15.5# & 14# J=55 casing to 7240' gel cement, bumped plug with 3000	psi -
Drilled 8 Demented held OK. bumped plo /8/60 Drilled o	thru shoe wit Cemented thrug with 3000 ut to 7210'.	th 398 sacks 6% tu stage collar psi - held OK.  Tested casing	" 15.5# & 14# J=55 casing to 7240' gel cement, bumped plug with 3000 at 2806' with 150 sacks 6% gel cement to 3000' psi = 0K.	psi - ent,
Drilled 8 Demented held OK. bumped plo /8/60 Drilled of	thru shoe wit Cemented thrug with 3000 ut to 7210.	th 398 sacks 6% tu stage collar psi - held OK.  Tested casing	" 15.5# & 14# J=55 casing to 7240' gel cement, bumped plug with 3000 at 2806' with 150 sacks 6% gel cem	psi - ent,
Drilled 8 Demented held OK. bumped plo /8/60 Drilled of	thru shoe wit Cemented thrug with 3000 ut to 7210'.	th 398 sacks 6% tu stage collar psi - held OK.  Tested casing	" 15.5# & 14# J=55 casing to 7240' gel cement, bumped plug with 3000 at 2806' with 150 sacks 6% gel cement to 3000' psi = 0K.	psi - ent,
Drilled 8 Cemented held OK. bumped plo /8/60 Drilled o	thru shoe wit Cemented thrug with 3000 ut to 7210.	th 398 sacks 6% tu stage collar psi - held OK.  Tested casing	" 15.5# & 14# J=55 casing to 7240' gel cement, bumped plug with 3000 at 2806' with 150 sacks 6% gel cement to 3000' psi = 0K.	psi - ent,
Drilled 8 Cemented held OK. bumped plu /8/60 Drilled of	thru shoe wit Cemented thrug with 3000 ut to 7210'.	th 398 sacks 66 to stage collar psi - held OK.  Tested casing	" 15.5# & 14# J=55 casing to 7240' gel cement, bumped plug with 3000 at 2806' with 150 sacks 6% gel cement to 3000' psi = 0K.	psi - ent,