

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 012736
2. NAME OF OPERATOR El Paso Natural Gas Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 990, Farmington, New Mexico 87401		7. UNIT AGREEMENT NAME Huerfano Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  800'N, 800'W		8. FARM OR LEASE NAME Huerfano Unit
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6368' D.F.	9. WELL NO. 138
		10. FIELD AND POOL, OR WILDCAT Undesignated Gallup
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22, T-26-N, R-9-W N.M.P.M.
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Abandon Dakota & Recomp. in Gallup

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

It is planned to plug and abandon the Dakota formation and recomplete in the Gallup formation in this well, as follows:

Pull tubing and set a cast iron retainer at 6300', squeeze the Dakota perf's (6410-6612') with 75 sacks of cement.

Selectively perforate and sand-water fracture the Gallup formation.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Petroleum Engineer

DATE October 8, 1971

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

OCT 8 1971

\*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

