




STATE OF NEW MEXICO  
ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE



BRUCE KING  
GOVERNOR

ANITA LOCKWOOD  
CABINET SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

December 9, 1992

Ms. Susan Woods  
Amoco Production Company  
San Juan Operation Center  
200 S. Amoco Court  
Farmington NM 87401

RE: Berger #4, C-22-26N-11W  
Michener A LS #4, H-28-28N-09W

Dear Susan:

1992 Packer Leakage Tests were not completed on the referenced wells. Please reschedule and test the wells as soon as possible. TA status does not exempt a well from testing.

Should both zones of a dually completed well be disconnected, it may be tested by shutting in both sides for a minimum of three days and blowing the higher pressured zone until the pressure decreases enough to determine if there is zone separation.

Yours truly,

Charles Gholson  
Deputy Oil & Gas Inspector

CG/sh

xc: well files