

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

July 12, 1963

*Tenneco Oil Company
P.O. Box 1714
Durango, Colorado*

Gentlemen:

Packer Leakage Test received in this office May 27, 1963 indicates that there is communication between the producing formations.

You are therefore directed to take immediate remedial action to separate the producing zones and upon completion of the workover to re-file packer leakage test.

Yours very truly

*Emery C. Arnold
Supervisor, District #3*

ECA:ks

*cc: Oil Conservation Commission ✓
Santa Fe, New Mexico*

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

July 12, 1967

James H. Brown
P.O. Box 1414
Durango, Colorado

Dear Sir:

Enclosed is a copy of a letterhead memorandum dated July 12, 1967, which states that there is communication between the producing formations.

You are therefore directed to take immediate remedial action to separate the producing formations upon completion of the workover to re-fill the lower leg with cement.

Yours very truly,

Walter G. Brown
Superintendent, District 18

cc: Mr. Brown
cc: Mr. Brown
cc: Mr. Brown