| W Wios | |
|---|--|
| | |
| NITED STATES ENT OF THE INTERIOR | PORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 |
| ENIND MAINAGEMENT | 5. Lease Designation and Serial No. |
| S AND REPORTS ON WELLS 15 50 0.00 | NM 013492 6. If Indian, Allottee or Tribe Name |
| drill or to deepen or reentry to a different reservoir. OR PERMIT—" for such proposals | |
| IT IN TRIPLICATE | 7. If Unit or CA, Agreement Designation |
| - 1. | West Bisti Unit |
| Lajection Well | 8. Well Name and No. |
| | West Bisti Unit 108 |
| | 30-045-05796 |
| NM 87499 (505) 325-1821 | 10. Field and Pool, or Exploratory Area |
| Description) | Bisti Lower Gallup |
| | 11. County or Parish, State |
| | San Juan, NM |
| (s) TO INDICATE NATURE OF NOTICE, REPOR | T, OR OTHER DATA |
| TYPE OF ACTION | |
| Abandonment | Change of Plans |
| Recompletion | New Construction |
| Plugging Back | Non-Routine Fracturing |
| Casing Repair | Water Shut-Off |
| Altering Casing V | Conversion to Injection |
| | Dispose Water (Note: Report results of multiple completion on Well |
| | Completion or Recompletion Report and Law form 1 |
| cal depth list all markers and zones pertinent to this work.)* | my proposed work. If well is directionally divided |
| of repairing casing or plugging isolate holes in casing. If cased with return to injection. If g. B cement plug across Gallup togelow Mesa Verde top at 2445' and plug inside and outside production elow Pictured Cliffs top at 1687 at plug to cover Fruitland top aduction. | ing can be un- at 4900'. I spot 100' on casing. |
| | INTED STATES ENT OF THE INTERIOR LAND MANAGEMENT S AND REPORTS ON WELLS drill or to deepen or reentry to a different reservoir. OR PERMIT—" for such proposals IT IN TRIPLICATE The jection. Wells NM 87499 (505) 325–1821 Description) (s) TO INDICATE NATURE OF NOTICE, REPORT TYPE OF ACTION Abandonment Recompletion Plugging Back Casing Repair Altering Casing Noter Test — Repair or Plug The rinded with, and give pertinent dates, including estimated date of starting a call depth with markers and zones pertinent to this work.)* What of repairing casing or plugging isolate holes in casing. If case ed with return to injection. If g. B cement plug across Gallup tore elow Mesa Verde top at 2445' and plug inside and outside producting elow Pictured Cliffs top at 1687 and plug inside and outside producting elow Pictured Cliffs top at 1687 and plug inside and outside producting elow Pictured Cliffs top at 1687 and plug inside and outside producting elow Pictured Cliffs top at 1687 and plug inside and outside producting elow Pictured Cliffs top at 1687 and plug inside cover Fruitland top as the plug to cover Fruitla |

14. I hereby certify that the foregoing is true and correct This space for Federal or State office use) 11/15/93 Operations Manager Date _ Approved by Conditions of approval, if any: Title

Tide 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the brited States are or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 La Plata Highway Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 108 West Bisti Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Mike Flaniken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made (when applicable):

1) Spot Gallup cement plug from PBTD to 5183'

Plus so Linear teet excess. (Gallup top à 5 3')

2.) Perforate à 538', place a coment plug from 566'

to 400' justide à out side the casin, plus 1002 excess.

(Bettim of 650 Alamo & 518')

Office Hours: 7:45 a.m. to 4:30 p.m.