

NEW MEXICO OIL CONSERVATION COMMISSION
WELL LOCATION AND ACREAGE DEDICATION PLAT

Form C-102
Supersedes C-128
Effective 1-1-65

CORRECTED COPY

All distances must be from the outer boundaries of the Section.


Operator SOUTHERN UNION PRODUCTION COMPANY			Lease NICKSON		Well No. 10
Unit Letter 0	Section 14	Township 26 NORTH	Range 8 WEST	County SAN JUAN	
Actual Footage Location of Well: 790 feet from the SOUTH line and 1735 feet from the EAST line					
Ground Level Elev. 6325.0	Producing Formation DAKOTA		Pool BASIN		Dedicated Acreage: 320 Acres

1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below.
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).
3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc?

☐ Yes ☐ No If answer is "yes," type of consolidation _____

If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.) _____

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commission.



CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

Original signed by
GILBERT D. NOLAND, JR.

Name
GILBERT D. NOLAND, JR.

Position
DRILLING SUPERINTENDENT

Company
SOUTHERN UNION PRODUCTION CO.

Date
MAY 27, 1968

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed
SEPTEMBER 15, 1963

Registered Professional Engineer
and/or Land Surveyor

Certificate No.

*TO CHANGE UNIT LETTER FROM P TO 0