60-5 90)

UNITED STATES DEPARTMENT OF THE INTERIOR RUREAU OF LAND MANAGEMENT

PORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT 5. Lease Designation and Serial No. NM 013492 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well West Bisti Unit APRZ 3 1993 Well Well 8. Well Name and No. 2. Name of Operator West Bisti Unit 102 CON. DIV. Dugan Production Corp. 9. API Well No. 3. Address and Telephone No. 30-045-05841 P.O. Box 420, Farmington, NM 87499 10. Field and Pool, or Exploratory Area (505) 325-1821 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Bisti Lower Gallup 11. County or Parish, State 1980' FSL - 1165' FWL Sec. 18, T26N, R13W, NMPM San Juan, NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other Cancel P&A & return to Dispose Water production (Note: Report results of a Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Request permission to cancel plugging sundry and return well to production. Only two holes were discovered in casing while pressure testing in preparation to plug. Repair casing as follows: Squeeze 29 cu. ft. Class B cement into Mesa Verde through hole at 2500° by using a packer to isolate 1. 2. Pump Class B cement down 5% production casing and return to braden head valve through hote in the Alamo 2 390. Drill out cement past hole at 390 and pressure test casing. Drill through squeeze at 2500' and pressure test complete casing string to 500 psi. 4. Drill cement and cast iron bridge plug that had been used to temporarily abandon the Gallup. 5. Swab test Gallup and acidize if needed. 6. 7. Return to production. 14. I hereby certify that the foregoing is true and correct Title Operations Manager 4/22/93 (This space for Federal or State office use) Title

Tide 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United Sche any part indicates or representations as to any matter within its jurisdiction.

5.00