

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-735-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐ Plugged and Abandoned 99 JAN 25 AM 11:07

2. NAME OF OPERATOR
Chevron U.S.A. Inc., Room 13097

3. ADDRESS OF OPERATOR
P. O. Box 599, Denver CO 80201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1,980' FSL, 660' FEL (NE, SE)

14. PERMIT NO.
30-045-05849

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6,423' KB

7. UNIT AGREEMENT NAME

West Bisti

8. FARM OR LEASE NAME

WBW

9. WELL NO.

101

10. FIELD AND POOL, OR WILDCAT

West Bisti

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 13-T26N-R14W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

The WBW #101 was plugged and abandoned on 1-17-89 as follows:

1. MIRU Welltech 98 on 1-11-89.
2. Killed well. N/D tree. N/U BOPE.
3. Released pkr @ 5,192. Pulled injection tbq until pkr stuck in damaged csg @ 228'
4. Chemically cut tbq above pkr. Attempted to fish pkr out of hole. Jarred prk in two.
5. L/D remainder of tbq.
6. Plugged well from surface w/750 sx 'G'. (115 sx sqzed into perfs @ 5,238-50'.)
7. Pressure tested 9 5/8" x 5 1/2" annulus to 400 psi. Unable to pump in.
8. Cut off wellhead. Installed dry hole marker.
9. Released rig.

Abandonment procedure verbally approved by Charles Brownson with New Mexico Oil and Gas
Division on 1-17-89.

RECEIVED
FEB 08 1989
OIL CON. DIV.
DIST. 3

6-BLM

1-EEM

1-JTL

2-Drig

1-PLN

1-Sec. 724-C

1-Sec. 724-R

1-File

1-COS

18. I hereby certify that the foregoing is true and correct

SIGNED *J. L. Watson*

TITLE Technical Assistant

DATE 1-19-89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side