	4				
TA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 N Effective 1-1-65			
		5a. Indicate Type of Lease			
LAND OFFICE		State Fee X			
OPERATOR		5. State Oil & Gas Lease No.			
	SUNDRY NOTICES AND REPORTS ON WELLS				
(HT SEU TON OC)	SUNDRY NOTICES AND REPORTS ON WELLS S FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERV. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7, Unit Agreement Name			
WELL	SAS OTHER-	7. GIAL AGLEEN AGINE			
2. Name of Operator	* ** 1 * 1 * CYP1 / A Y	8. Farm or Lease Name			
J. FE	LIX HIGKMAN	Malco State Comm.			
P.O.	BOX 1641 BLOOMFIELD, NEW MEXICO 874	9. Well No. /			
4. Location of Well	1250	10. Field and Pool, or Wildcat			
INIT LETTER		FEET FROM			
THE	LINE, SECTION 16 TOWNSHIP 26-N RANGE 8-W	NMPM.			
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County			
	6495 Gr.	San Juan			
16	Check Appropriate Box To Indicate Nature of Notice, Rep	· · · · · · · · · · · · · · · · · · ·			
ИО		SSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING			
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.				
# . OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT .	JGB []			
STHER					
.'. Testrice Proposed of work) SEE RULE 11	Completed Operations (Clearly state all pertinent details, and give pertinent date 03.	es, including estimated date of starting any propose			
6/5/78	Move in and rig up plugging rig				
ं/6/7 उ	Pull and lay down 1" tubing.				
6/9/78	Pick up 2 3/8" tubing, tag bottom at 2387. Mix and spot 30 sacks cement on				
bottom. Lay down 2 3/8" tubing. 6/10/76 Perforate 4 1/2" casing at 1752 ft. Mix and spot 35 sacks cement at 1753					
0, 20, 10	Close valve on back side, squeeze approximatly	17 sacks out holes in casing.			
	Pull tubing out of hole. W.A.C.				
6/11/78	Ran sinker bars on wire line, found top of ceme	ent at 1523 ft. Shot casing			
6/12/78	in to at 447 ft. Lay down $4\frac{1}{2}$ " casing. Finished laying down $4\frac{1}{2}$ " casing. Ran in 4 jts. 2 3/8" tubing. Mix and spot				
	30 sacks cement at 114 ft. Mix and spot 10 sack	s cement in top of surface			
6/13/76	pipe. Rig down Install dry hole marker, clean, level and back drag location.				
		Man The Co			
		JUL CONST. 2			
erosa certus inut t	ie internation above is time and complete to the best of my knowledge and hellef,	CITY OF			

DALL TIONS OF APPROVAL, IF ANYI

Original is

NEW MEXICO OIL CONSERVATION COMMISSION

	<i>ሽ ሚ</i> ጥርር እነር	RAZOS ROAD W MEXTOO	Flour	Shee @ 2408	
() Do april		W HEALEO		3116 6 2408	
Delix Hickory De Bloomfield dis Box 1641	Lied Service	e Cô.			
Bax 1641					
Bloomfield, 71.	· M.	Re: Plugging	Reports		
Gentlemen:				,	
Form C-103, Notice of	Intention to Plug,	your <u>Malor</u> Lease	State C	Well No.	
G-16-26N-84	was approved	3-9-1	S	. Your	
Unit S-T-R subsequent notice of p	,				
tive has made an inspe	ction of the locat	ion to see:			
(1) a	ll pits have been	filled and le	veled;		
a ti o ni	steel marker, 4 ⁿ bove mean ground l his marker must ha r unit designation umbers, which shal elded on the marke	evel, must be ve the quarte: , section, to l be permanen	set in co r-quarter wnship and	oncrete, section d range	
(3) ti	he location shall	be cleared and	d cleaned	of all junk;	
(4) ti	he dead man wires	must be cut.			
The above are the minimum	mum requirements.				
Please notify us by filling in the blank form below when this work has been					
done so that our representative will not have to make more than one trip to					
the location.		· · ·			
Fill in Below and return Malco STate Com	rn: #/ 6 26N 8	В	Rte	COMMISSION Addition	
Lease Well No. approval.	unit s-T-k	Bloom Operation	MF, old tor Day to	0:15:16 Savice Dresident	