

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. SF-078622
2. NAME OF OPERATOR GREAT WESTERN DRILLING CO.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 3535 E. 30th St. Suite 242 Farmington, NM 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface: 1160' FNL & 960' FFL		8. FARM OR LEASE NAME Bond Federal
14. PERMIT NO.		9. WELL NO. 2
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6259' G.L.		10. FIELD AND POOL, OR WILDCAT Basin Dakota + Ballard Pictured Cliffs
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13, T-26N, R-8W
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☒

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Move in work over rig, pull both tubing strings, set bridge plug to protect Dakota zone, find and squeeze holes in csg. drill out cement and test both zones, put well back on production.

RECEIVED  
MAIL ROOM  
69 FEB -3 PM 2:15  
FARMINGTON RESOURCE AREA  
FARMINGTON, NEW MEXICO

RECEIVED  
FEB 15 1989  
OIL CON. DIV.  
ALBUQ.

18. I hereby certify that the foregoing is true and correct

SIGNED

*D. E. Baxter*

TITLE Dist. Superintendent

DATE February 3, 1989

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

FEB 13 1989

AREA MANAGER

\*See Instructions on Reverse Side