

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-078953

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR
Skelly Oil Company

8. FARM OR LEASE NAME

J. W. Goddard

3. ADDRESS OF OPERATOR
1860 Lincoln Street - Denver, Colorado 80203

9. WELL NO.

3

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT

Gallegos Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 11-26N-12W

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6059' GR

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)
PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)
REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well reached the economic limit and no longer is profitable to operate.

Plans are to plug and abandon this well and plug as follows:

- First Plug - Across Gallup Zone perfs. 5188'-5151' filling up 50' to 5101'.
- Second Plug - 50' inside 5 1/2" casing and 50' above where casing is shot in two.
- Third Plug - 100' plug above top of Mesa Verde formation (unless production casing is left remaining through this zone).
- Fourth Plug - 100' plug at the bottom of Ojo Alamo Sand (unless surface casing is set through the Ojo Alamo Sand).
10 sacks of cement in top of surface casing with dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE District Superintendent

DATE Nov. 17, 1967

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

DATE RECEIVED

NOV 22 1967

*See Instructions on Reverse Side