
Form 9-881 a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Pe
Lease No.	078944-A
Unit	Melson

	ENTION TO DRILLENTION TO CHANGE PLAN		li		SHUT-OFF	
	ENTION TO CHANGE PLAN		H		ING OR ACIDIZING.	
	ENTION TO RE-DRILL OR		fl		NG CASING	
	ENTION TO RE-BRILL OR ENTION TO SHOOT OR AC		11		LLING OR REPAIR	
	ENTION TO PULL OR ALTE				ONMENT	
	ENTION TO ABANDON WEL	1				
					-	•
	(INDICATE A	BOVE BY CHECK MARK N	NATURE OF REPORT	, NOTICE, OR OTHER	DATA)	
					June 11	, 19_
il No	1-A is located	1980 ft. from	line and	1978 ft. fr	om (line of	sec. 9
154	Sec. 9	268	128	N.F.K.	(**)	
	nd Sec. No.) ldcat	(Twp.) (F	Range)	(Meridian)	ase Marel as	
	ield)		Subdivision)		(State or Territory)	
6-	5-57. Total D	epth 4027'.	ner important pro	·		
6 Ra 40 ge	5-57. Total B n 92 joints, 7 26' with 100 s 1, 1/4#/sk. fl 1d 1000# for 3	epth 4027'. '-5/68, 26.40# mcks regular ocale followe	, J-55 cas cement, 10	ing (4014') O sacks Pos	mix, 4%	
6 Ra 40 ga Ba	n 92 joints, 7 26' with 100 s 1, 1/4#/sk. 11	epth 4027'. '-5/68, 26.40# mcks regular coele followe O minutes.	, J-55 cas cement, 10 d by 50 sa	ing (4014') O sacks Pos cks regular	mix, 4%	
6 Ra 40 ga Ba	n 92 joints, 7 26' with 100 s 1, 1/4/sk. fl 1d 1000# for 3	epth 4027'. '-5/68, 26.40# mcks regular coele followe O minutes.	, J-55 cas cement, 10 d by 50 sa	ing (4014') O sacks Pos cks regular	mix, 4%	01.0
6 Ra 40 ga Sa	n 92 joints, 7 26' with 100 s 1, 1/4/sk. fl 1d 1000# for 3	epth 4027'. '-5/68, 26.40# mcks regular coele followe O minutes.	, J-55 cas cement, 10 d by 50 sa	ing (4014') O sacks Pos cks regular	mix, 4%	OUL CON
6 Ra 40 ge He To	n 92 joints, 7 26' with 100 s 1, 1/4#/sk. fl 1d 1000# for 3 p of cement by	epth 4027'5/68, 26.40# scks regular coals follows: 0 minutes. temperature	, J-55 cas cement, 10 d by 50 sa survey at	ing (4014') 0 sacks Pos cks regular 2160'.	mix, 45 coment.	OM CON S
6	n 92 joints, 7 26' with 100 s 1, 1/4/sk. fl 1d 1000# for 3 p of cement by	epth 4027'5/68, 26.40# scks regular ccele followe minutes. temperature	, J-55 cas cement, 10 à by 50 sa survey at	ing (4014') 0 sacks Pos cks regular 2160'.	mix, 45 coment.	Commence
6-Ra 40 ge Ha To	n 92 joints, 7 26' with 100 s 1, 1/4/sk. fl 1d 1000# for 3 p of cament by hat this plan of work mu El Paso Sat	epth 4027'5/68, 26.40# scks regular coals follows: 0 minutes. temperature	, J-55 cas cement, 10 à by 50 sa survey at	ing (4014') 0 sacks Pos cks regular 2160'.	mix, 45 coment.	Commence
6-Ra 40 ge He To	n 92 joints, 7 26' with 100 s 1, 1/4/sk. fl 1d 1000# for 3 p of cement by	epth 4027'5/68, 26.40# scks regular ccele followe minutes. temperature	, J-55 cas cement, 10 à by 50 sa survey at	ing (4014') 0 sacks Poseks regular 2160'.	cessent.	The same of the sa
6-Ra 40 ge Ha To	n 92 joints, 7 26' with 100 s 1, 1/4/sk. fl 1d 1000# for 3 p of cament by hat this plan of work mu El Paso Sat	epth 4027'5/68, 26.40# acks regular coele followe o minutes. temperature at receive approval in warral. Gas Compa	, J-55 cas cement, 10 à by 50 sa survey at	ing (4014') 0 sacks Poseks regular 2160'.	coment.	C!^!
I understand the mpany	n 92 joints, 7 26' with 100 s 1, 1/4/sk. fl 1d 1000# for 3 p of cement by hat this plan of work mu El Paso Mat Box 997	epth 4027'5/68, 26.40# acks regular coele followe o minutes. temperature at receive approval in warral. Gas Compa	, J-55 cas cement, 10 d by 50 sa survey at	ing (4014') 0 sacks Post cks regular 2160'.	cessent.	C. 45'