Form 9-331a (Feb. 1951)	5-USGS 1-Gulf 1-EPHG Prod. 1-MD (SUBMIT IN TRIPLICATE) 1-D UNITED STATES 1-F UNITED STATES DEPARTMENT OF THE INTERIOR	Land (Lease I Unit Black	
SUND	RY NOTICES AND REPORTS	ON W	ELLS

(-	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS.	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALIER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	FA CCC OCHEAN
(INDICATE ABOVE BY CHECK MARK NATU	DE CE DEPORT NOTICE OR OTHER DATA
(10.00.2.20.0.20.0.10.0.0.0.0.0.0.0.0.0.0	10 to
<u></u>	September 25 , 19.62
Well No. 1 is located	line and 790 ft. from $\{E\}$ line of sec. 7
NE/4 NE/4 Sec. 7 26 N 1 (½ Sec. and Sec. No.) (Twp.) (Range	(Meridian)
	e) (Meridian)
Baein Dekota San Nan	livision) (State of Territory)
DETAILS (State names of and expected depths to objective sands; show sizes, wei ing points, and all other in	ghts, and lengths of proposed casings; indicate mudding jobs, cement
State names of and expected depths to objective sands; show sizes, well ing points, and all other in	ights, and lengths of proposed casings; indicate mudding jobs, cement important proposed work)
State names of and expected depths to objective sands; show sizes, well ing points, and all other in Propose to plug and abandon well in Squeeze perfs. 6090-991.	the following manner:
State names of and expected depths to objective sands; show sizes, well ing points, and all other in Propose to plug and abandon well in Squeeze perfs. 6090-99'. 100' plug 50' in and 50'	the following manner:
Propose to plug and abandon well in Squeeze perfs. 6090-99'. 100' plug 50' in and 50' Plug 1000' to 1100'	the following manner: RECEIVED out casing stub.
State names of and expected depths to objective sands; show sizes, well ing points, and all other in Propose to plug and abandon well in Squeeze perfs. 6090-99'. 100' plug 50' in and 50'	the following manner: RECEIVED out casing stub.
Propose to plug and abandon well in Squeeze perfs. 6090-99'. 100' plug 50' in and 50' Plug 1000 to 1100'	the following manner: RECEVED out casing stub. SEP 27 1962 OIL CON. COM. DIST. 3
Propose to plug and abandon well in Squeeze perfs. 6090-99'. 100' plug 50' in and 50' Plug 1000 to 1100' Plug at surface with mark	the following manner: RECEVED out casing stub. SEP 2 7 1962 OIL CON. COM. DIST. 3
Propose to plug and abandon well in Squeeze perfs. 6090-99'. 100' plug 50' in and 50' Plug at surface with mark	the following manner: RECEVED out casing stub. SEP 27 1962: OIL CON. COM. DIST. 3
Propose to plug and abandon well in Squeeze perfs. 6090-99'. 100' plug 50' in and 50' Plug 1000 to 1100' Plug at surface with mark I understand that this plan of work must receive approval in writin Company	the following manner: CEVED out casing stub. SEP 27 1962 OIL CON. COM. DIST. 3 Original signed by
Propose to plug and abandon well in Squeeze perfs. 6090-99'. 100' plug 50' in and 50' Plug 1000 to 1100' Plug at surface with mark I understand that this plan of work must receive approval in writin	the following manner: RECEVED out casing stub. SEP 27 1962: OIL CON. COM. DIST. 3