

1. FIRM OR PERSON'S NAME  
2. FIRM OR PERSON'S ADDRESS  
3. CITY, STATE, ZIP CODE  
4. COUNTY OR PARISH, STATE

5. FIRM OR PERSON'S NAME  
6. FIRM OR PERSON'S ADDRESS  
7. CITY, STATE, ZIP CODE

8. FIRM OR PERSON'S NAME  
9. FIRM OR PERSON'S ADDRESS  
10. CITY, STATE, ZIP CODE

11. 660°N, 1833°E, 12-W

12. PERMIT NO.

13. ELEVATIONS (Show whether DE, RT, GA, etc.)

14. 5991' GL

15. 12-26-N, 12-W

16. COUNTY OR PARISH, STATE

17. San Juan New Mexico

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Document

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WELL SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ABANDON

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

19. MISCELLANEOUS OR COMPLETED OPERATIONS (Clean, state all pertinent details, and give pertinent date, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

(Est. date to start work  
4-1-68)

1. Load hole with mud laden fluid.
2. Squeeze Gallup perforations.
3. Shoot pipe loose at free point and pull.
4. Spot 100' cement plug 50' in and 50' out of stub.
5. Spot 100' cement plug across top of picture cliff.
6. Spot 100' cement plug at base of Ojo Alamo.
7. Place cement plug in top of surface with welded marker in place.
8. Clean location.

RECEIVED

MAR 29 1968

U. S. GEOLOGICAL SURVEY

RECEIVED

APR 1 1968

OIL CON. COM  
DIST. 3

20. I hereby certify that the foregoing is true and correct

Signature

Printed Name Agent

Date 3-20-68

(This space for Return or Sure Date use)

21. THE FOLLOWING INFORMATION OR INSTRUCTIONS, IF ANY:

TIME

DATE

\*See instructions on Reverse Side