5. LEASE

## UNITED STATES

DEPARTMENT OF THE INTERIOR	SF 081101
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
CUMPON MOTIOES AND DEPORTS ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	
o not use this form for proposals to drill or to deepen or plug back to a different ervoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
oil gas well other	Chartier
NAME OF OPERATOR	
Merrion Oil & Gas Corporation	10. FIELD OR WILDCAT NAME
ADDRESS OF OPERATOR	North Bisti X al Veaci Jall
P. O. Box 1017, Farmington, New Mexico 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR
LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 4, T26N, Rl2W
below.)	
AT SURFACE: 2310' FSL and 330' FEL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE 2 San Juan = 7.7 New Mexico
AT TOTAL DEPTH: Same	<del></del>
Same . CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	TE ELEVATIONS (CHOW DE KDR AND WO)
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW_DF, KDB, AND WD) 6027 GR
QUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
ST WATER SHUT-OFF	·
ACTURE TREAT	그 그 그 그 이 무슨 사람들은 그 그 그가 되었다.
OOT OR ACIDIZE	
	(NOTE: Report results of multiple completion or zone
LL OR ALTER CASING	change on Form 9–330.)
ILTIPLE COMPLETE	원 시 전 시 시 시 를 통원들이 중시고등 원호 시
ANGE ZONES	
ANDON* X Detail Alexander	化二十二二二烷基 化氯基基基苯二烷二基苯基苯甲二
ther)	មានស្ត្រីម៉ើល ប្រាប់
7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is discussived and true vertical depths for all markers and zones pertinent Propose to plug and abandon as follows:  1. Spot 37 sx plug from 5175 to 4850' to cove	r Gallup interval
2. Perforate @ 4100 ft. and place 40 sx insid	
3980' to cover Mesaverde - Mancos Boundary	
3. Perforate @ 2250' and place 40 sx plug ins	ide and outside from 22507 - 2130
to cover top of Mesaverde.	
4. Shoot off casing @ 1350' and place 43 sx f	rom 1350 - 1230 to cover picture
Cliffs - Fruitland Boundary.	
5. Spot 75 sx plug from 375' - 150' to cover	
6. Place 10 sx surface plug and erect dry hol	e marker.
7. Reclaim surface per your instructions.	교교육실육 성연 실험실증 기
9.2 #/gal. mud to be placed between plugs.	
ubsurface Safety Valve: Manu. and Type	Set @ Ft.
8. I hereby certify that the foregoing is true and correct	
GNED TITLE Operations Ma	nager <sub>DATE</sub> 5/30/84
(This space for Federal or State off	ice use)
PPROVED BY	DATE
ENOTION E APPROVAL IF ANY:	
W	AND THE RESTRICTION AS A SEE A SPECIAL OF THE SECOND AS A SECOND A
JUN 1 9 1984 *See Instructions on Reverse	side (SGD.) MATHEW N. MILLENBA

Off CON. DIV.

2227

5/29/84

95/8"@ 192 W/ ZOSX CIRC.

TOC 4619 - CALCULATED

5123-5159

PBTD - 5175' 51/2" CSC & 5219' KB W 125 3X