Form	9-381 8
(Feb	. 1951)

1			į
1	 		
ı		}	ļ.
		;	
1	 		
			1
1			l
1	 		
-	i	!	i

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe
Lease No	078563
TT-te	Filen

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT	REPORT OF WATER SHUT-	OFF	7
OTICE OF INTENTION TO CHANGE	PLANS	11	REPORT OF SHOOTING OR	養養 2	i
OTICE OF INTENTION TO TEST W	ATER SHUT-OFF	SUBSEQUENT	REPORT OF ALTERING CAS	NG	
OTICE OF INTENTION TO RE-DRIE	L OR REPAIR WELL	SUBSEQUENT	REPORT OF RE-DRILLING	OR REPAIR	
OTICE OF INTENTION TO SHOOT	OR ACIDIZE	SUBSEQUENT	REPORT OF ABANDONMEN	r	
OTICE OF INTENTION TO PULL O	R ALTER CASING	SUPPLEMENTA	RY WELL HISTORY		
OTICE OF INTENTION TO ABANDO	N WELL				
(INDI	CATE ABOVE BY CHECK MARK I	NATURE OF REPORT	, NOTICE, OR OTHER DATA)		
		*****************	July 11		, 19
ell Nois loc	ated 3530 ft. from.	N line and	1050 ft. from [I	ine of sec.	5
Sec. 7	27त	3v	B.M.P.M.		
(1/2 Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)		
Blanco (Field)	See Je	Subdivision)	See 1	or Territory)	
	DETAIL	LS OF WOR	K gths of proposed casings; i	ndicate mudding jol	s, cem
te names of and expected depths On 7=3=53. Total 1	DETAIIs to objective sands; show size ing points, and all of	LS OF WOR	K gths of proposed casings; i posed work) [50 1] set at 23	60' with 75	asci
on 7-3-53. Total 1 Ren 70 joints 7 5/6	DETAIIs to objective sands; show size ing points, and all of	LS OF WOR	K gths of proposed casings; i posed work) [50 1] set at 23	60' with 75	taci
on 7-3-53. Potal 1 Run 70 joints 7 5/6 reg. coment, 75 sks	DETAIL to objective sands; show size ing points, and all of the sand in the s	LS OF WOR	K gths of proposed casings; i posed work) [50 1] set at 23	60' with 75	a a el
on 7-3-53. Total 1 Run 70 joints 7 5/6 reg. cement, 75 sks Rest cement.	DETAIL to objective sands; show size ing points, and all of the sand in the s	LS OF WOR	K gths of proposed casings; i posed work) [50 1] set at 23	50' with 75 st	age!
On 7-3-53. Total 1 Sen 70 joints 7 5/6 reg. cement, 75 sks Seld 1000 for 30 s	DETAIL to objective sands; show size ling points, and all of lepth 232'. Frankler, 50 Flacture survey	LS OF WOR	K gths of proposed casings; is posed work) Set at 23 RELLI OIL CON DIST	Sor with 75 a with 50 si	taci
on 7-3-53. Potel 1 Ren 70 joints 7 5/6 reg. cessent, 75 sks Reat cessent. Reld 1000 for 30 s Top of occase by to	DETAIL to objective sands; show size ling points, and all of lepth 232'. Frankler, 50 Flacture survey	LS OF WOR	K gths of proposed casings; is posed work) Set at 23 RELLI OIL CON DIST	Sor with 75 a with 50 si	taci
on 7-3-53. Total 1 Ren 70 joints 7 5/6 reg. coment, 75 ski Rest coment. Held 1000 for 30 s Top of occasit by ta	DETAIL to objective sands; show size ing points, and all of the sand ing points. The sand ing points, and all of the sand ing points, and all of the sand ing points. The sand ing points in the sand in	LS OF WOR	K gths of proposed casings; is posed work) Set at 23 RELLI OIL CON DIST	Sor with 75 a with 50 si	tet

Petroleum Roginser