	DELYLIMENT OF	THE INTERIO		Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
	BUREAU OF LAN	MANAGEMENT		NM-0359212
SUN (Do not use this	DRY NOTICES AND form for proposals to drill or Use "APPLICATION FOR PI	to deepen or plug bac ERMIT—" for such pro-	ck to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS		REC	EIVED	7. UNIT AGREEMENT NAME
WELL WELL NAME OF OPERATOR	OTHER			
		JAN	1 4 1987	8. PARM OR LEASE NAME
B. ADDRESS OF OPERATOR	opment Company	O 1	± 130/	Henderson Federal
238 Petro	oleum Plaza Farmi	BUREAU OF LAI	NO MANAGEMENT	1
LOCATION OF WELL (R. See also space 17 belo	oleum Plaza, Farmi eport location clearly and in a w.)	ccordance with any St	Me Odgreenep is	10. FIELD AND POOL, OR WILDCAT
At surface	,		- MCA	Basin Dakota
				11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA
790 '	FNL & 790' FEL			
4. PERMIT NO.	15 BLEVATIO	NS (Show whether DF, R	r CP eta)	Sec. 5, T-26N, R-11W 12. COUNTY OR PARISH 13. STATE
	1		1, GR, EUC.)	
		6234' GR		San Juan New Mexico
6.	Check Appropriate Bo	ox To Indicate Nat	ture of Notice, Report,	or Other Data
N-	OTICE OF INTENTION TO:	1	8 01	BREQUENT REPORT OF:
TEST WATER SHUT-OF	PULL OR ALTER	CASING	WATER SHUT-OFF	REPAIRING WELL
FR :CTUBE TREAT	MULTIPLE COMP	J.ETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	<u>X</u>	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS		(Other)	
(Other)			Completion or Rec	sults of multiple completion on Well completion Report and Log form.) ates, including estimated date of starting any
Propose to I	A rig, pull 2-3/8"	tubing, re-r	un w/cement retai	iner to top of Model "G"
Rig up P & A packer @ 619 Spot 35 sx of Free point a 100' plug 33 100' plug 17 100' plug 15 160' plug @ 110' plug @ 110' plug 20 Put 580' plug	A rig, pull 2-3/8" 94' pump 50 sx cem class "B" cement 5 and pull all recov 350-3250 or if csg 65-2565' or if csg 65-1465 or if csg 780-620 or if csg	ent class "B" 400-5010'. erable 4½" ca in place pe	into 4½" casing sing. so in and so arf 2 holes @ 3350 erf. 2 holes @ 179 erf. 2 holes @ 156 erf. 2 holes @ 780 erf. 2 holes @ 7	0 & squeeze 35 sx. 665' & squeeze 35 sx. 95' & squeeze 35 sx. 95 & squeeze 35 sx.
Rig up P & A packer @ 619 Spot 35 sx of Free point at 100' plug 33 100' plug 15 100' plug 15 160' plug @ 110' plug @ 110' plug 20 Put550' plug re-seed as d	A rig, pull 2-3/8" 94' pump 50 sx cem class "B" cement 5 and pull all recov 350-3250 or if csg 65-2565' or if csg 65-1465 or if csg 780-620 or if csg 19-99 50' in and 50 in top of surface irected by B.L.M.	ent class "B" 400-5010'. erable 4½" ca in place pe pripe w/dry b	into 4½" casing sing. so in and so arf 2 holes @ 3350 erf. 2 holes @ 179 erf. 2 holes @ 156 erf. 2 holes @ 780 erf. 2 holes @ 7	perforations @ (6273-6354) Cover of any serve A squeeze 35 sx. 5' & squeeze 35 sx. 5' & squeeze 35 sx. 5' & squeeze 35 sx. 1' & squeeze 35 sx.
Rig up P & A packer @ 619 Spot 35 sx of Free point at 100' plug 33 100' plug 17 100' plug 15 160' plug @ 110' plug 20 Put 520' plug re-seed as d	A rig, pull 2-3/8" 94' pump 50 sx cem class "B" cement 5 and pull all recov 350-3250 or if csg 65-2565' or if csg 65-1465 or if csg 780-620 or if csg 19-99 50' in and 50 in top of surface irected by B.L.M.	ent class "B" 400-5010'. erable 4½" ca in place pe pripe w/dry b	sing. o'in and so rf 2 holes @ 3350 erf. 2 holes @ 26 rf. 2 holes @ 179 rf. 2 holes @ 156 rf. 2 holes @ 780 face pipe @ 209'. hole marker, leve	perforations @ (6273-6354) Cott of A. 3 Stob 0 & squeeze 35 sx. 665' & squeeze 35 sx. 15' & squeeze 35 sx. 15' & squeeze 35 sx. 1 & clean up location,
Rig up P & A packer @ 619 Spot 35 sx of Free point at 100' plug 33 100' plug 15 100' plug 15 160' plug @ 110' plug 20 Put 520' plug re-seed as d I hereby certify that the SIGNED (This space for Federal	A rig, pull 2-3/8" 94' pump 50 sx cem class "B" cement 5 and pull all recov 350-3250 or if csg 65-2565' or if csg 65-1465 or if csg 780-620 or if csg 9-99 50' in and 50 in top of surface irected by B.L.M.	ent class "B" 400-5010'. erable 4½" ca in place pe pripe w/dry b	sing. o'in and so rf 2 holes @ 3350 erf. 2 holes @ 26 rf. 2 holes @ 179 rf. 2 holes @ 156 rf. 2 holes @ 780 face pipe @ 209'. hole marker, leve	perforations @ (6273-6354) Cott of A. 3 Stob 0 & squeeze 35 sx. 665' & squeeze 35 sx. 15' & squeeze 35 sx. 15' & squeeze 35 sx. 1 & clean up location,
Rig up P & A packer @ 619 Spot 35 sx of Free point at 100' plug 33 100' plug 17 100' plug 15 160' plug @ 110' plug 20 Put 520' plug re-seed as d	A rig, pull 2-3/8" 94' pump 50 sx cem class "B" cement 5 and pull all recov 350-3250 or if csg 65-2565' or if csg 65-1465 or if csg 780-620 or if csg 9-99 50' in and 50 in top of surface irected by B.L.M.	ent class "B" 400-5010'. erable 4½" ca in place pe g. in place pe of out of surre e pipe w/dry b	sing. o'in and so rf 2 holes @ 3350 erf. 2 holes @ 26 rf. 2 holes @ 179 rf. 2 holes @ 156 rf. 2 holes @ 780 face pipe @ 209'. hole marker, leve	perforations @ (6273-6354) Cott of A. 3 Stob 0 & squeeze 35 sx. 665' & squeeze 35 sx. 15' & squeeze 35 sx. 15' & squeeze 35 sx. 1 & clean up location,

Title 18 U.S.C. Section 1001, makes it a crime for any person will go and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.